

Incident Number
2022/LA210131

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: MAGDAH NAIP OIL COMPANY

2. Type of Complaint/Incident:

☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Related/Technical Problem
☒ Others (Specify)

3. Incident Details

I. Date of Incident: 2/2/2022 II. Date first reported: 2/2/2022

III. Date of first investigation: 4/2/2022

IV. Date of follow-up investigation:

V. Time investigation started: 3:30 PM

VI. Estimated quantity spilled: 2 BARREL 2006° 27' 50"

4. Site Details: 1 N05° 05' 54.2" E 006° 27' 43.2" N05° 06' 03.4,

I. Site location: CSMAE / 55 F/L AT ALKUMMA, ADELGAH R/S STATE

II. Position of spill: 60' clock, 70' clock

III. Spill area

☒ T and ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Corals
☒ Near shore ☒ Offshore ☐ Others (Specify)

IV. Structural Controls in Place

☒ Boom ☒ Fences ☒ Blind Wall ☒ Sorbents ☒ Others (Specify) NIL

5. Circumstances Around Spill Point

I. Visual observation of Spill Position

☒ 120' Clock ☒ 100' Clock ☒ 20' Clock ☒ 30' Clock
☒ 40' Clock ☒ 50' Clock ☒ 60' Clock ☒ 70' Clock

II. Type of Oil & Contaminant

☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (Specify)

III. Facility

☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Production ☒ Flow Station ☒ Rig

☒ Storage Tank ☒ Compressor Plant

☒ Others (Specify)

IV. Cause of Spill

☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident

☒ Operational Error ☒ Others (Specify)

Visible Signs of Third Party Interference

☒ Hack Saw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid

☒ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the Incident

☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water

☒ Venerable Objects ☐ Others (Specify)

ii. Nature of impact

☒ Oil stained vegetation

☒ Oil stained fishing nets

☒ Dead floating fishes

☒ Dead floating crabs

☒ Withering of vegetation

☐ Others (Specify)

iii. Definition of impacted area

☒ Within Company's facility/ROW

☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. ALINIMA, AVELERA

(b) Land (Indicate area in m²)

i. 13-97

ii.

iii.

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken..... NO

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation.....

Clean up of impacted area. Immediate
Improve on surveillance.

12. Time investigation ended..... 4:15pm

13. Name and Signature of Participants