


OVERFLY of SEPCOL FPSO OIL SPILL INCIDENT ON 04/02/2022



OVERFLIGHT OBSERVATION

- 1.The team left shell I.A Ogunu air Operation by 1637hrs.
- 2.A Vessel was observed partially submerged in the water.
- 3.Crude oil Sheen was seen on water.
- 4.Sheen was drifting South-west as at the time of overfly
- 5.No boat or clean-up exercise was observed.
- 6.The Flight covered the point of incident and extend of impact.
- 7.Approximate coordinate of spill point:4.8312E, 5.72649N(WGS84)
- 8.Team arrive shell I.A by 1800hrs.

Area measurement
Segment: 1,390.734222 Meters
Perimeter: 15,366.06822 Meters
Area: 780.604969 Hectares

EXTEND OF OIL SHEEN

OIL SHEEN ON WATER

Spill point

ADAGBASA M/F

BOBI
CREEK-001

BENIN
ESTUARY-001

AGOGBORO-001

OTUMARA-010
OTUMARA-013
OTUMARA-005
OTUMARA-017
OTUMARA-008
OTUMARA-006

SAGH
SA
SAGH
S
SA