



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY (NOC) LTD.
2. Type of Complaint/Incident:
☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify).....
3. Incident Details
i. Date of Incident: 12/07/21 ii. Date first reported: 12/07/21
iii. Date of first investigation: 12/07/21 iv. Spill Incident No: 2021/SAR/042
v. Date of follow-up investigation: —/—/—
vi. Time investigation started: 1450 HRS
vii. Estimated quantity spilled(bbls): 16 viii. Quantity Recovered: ON GOING
4. Site Details
i. Site/Location: OGBONBIRI WELL 4 ESP @ OGBONBIRI
ii. State: BAYELSA iii. L.G.A: SOUTHERN ITAW
iv. Spill Co-Ordinates: N(m) 04° 49' 02.2"
E(m) 005° 58' 44.5"
v. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify).....
iv. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify).....
iii. Facility
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....
iv. Cause of Spill
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify).....
v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify).....



6. Impact of Incident

i Properties impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
☒ Others (specify)

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
☒ Withering of vegetation
☒ Others

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW
☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops
☒ Fish Farm/ Pond
☒ Fishing Net
☒ Makeshift
☒ Permanent
☒ Others

8. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m^2)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

- ☒ Tidal
☒ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

- ☒ Tidal
☒ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

- ☒ Tidal
☒ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken..... NOT APPLICABLE

11. Investigation carried out by

☐ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation..... VANDALS USED HACKSAW TO
CUT OFF THE CCH ON THE WELLHEAD.
CLEAN UP AND REMEDIATION IS REQUIRED

13. Time investigation ended.....