



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This JIV form is to be completed and signed by all participating parties in the field*

1. Company: SPDC
2. Type of Complaint/Incident: INCIDENT NO. 3085302
- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
- ☒ Others (Specify) OIL POLLUTION (NON-LEAKING)
3. Incident Details
- i. Date of Incident: 22/02/2022 ii. Date first reported: 23/02/2022
- iii. Date of first investigation: 25/02/2022
- iv. Date of follow-up investigation: 12.6 HRS.
- v. Time investigation started: 12.6 HRS.
- vi. Estimated quantity spilled: NIL
4. Site Details
- i. Site/Location: 20" RUMUEKPE-NKPOKY PIPELINE AT IBA
- ii. Position of Spill/Leak: 4.954082 N 6.821203
- iii. Spill area
- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
- ☐ Near shore ☐ Offshore ☐ Others (Specify) .....
- iv. Structural Controls in Place NOT APPLICABLE
- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) .....
5. Circumstances Around Spill Point
- i. Visual observation of Hole Position
- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
- ☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock
- ii. Type of Oil Contaminant
- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
- ☒ Others (Specify) NO SPILL
- iii. Facility
- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
- ☐ Storage Tank ☐ Compressor Plant
- ☐ Others (Specify) .....
- iv. Cause of Spill
- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
- ☐ Operational Error ☐ Others (Specify) .....
- v. Visible Sign of Third Party Interference
- ☐ Holes ☐ Drilled Holes ☐ Planting ☒ Theft ☐ Acid

## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☐ Farmland   ☐ Fish Pond   ☐ Vegetation   ☐ Fishing Net   ☐ Surface water  
☐ Venerable Objects   ☐ Others (Specify) .....

NOT APPLICABLE

### ii. Nature of impact

- ☐ Oil stained vegetation   ☐ Oil stained fishing nets   ☐ Dead floating fishes  
☐ Dead floating crabs   ☐ Withering of vegetation   ☐ Others (Specify) .....

NOT APPLICABLE

### iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW   ☐ Outside Company's facility/ROW

NOT APPLICABLE

## 7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m<sup>2</sup>)

- i. ....  
 ii. ....  
 iii. ....  
 iv. ....

NOT APPLICABLE

NOT APPLICABLE

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

| NAME           | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|----------------|--------------------|-----------------|----------------|
| NOT APPLICABLE |                    |                 |                |

(d) Swamp

☐ Tidal

☐ Non-tidal

| NAME           | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|----------------|--------------------|-----------------|----------------|
| NOT APPLICABLE |                    |                 |                |

(e) River

☐ Tidal

☐ Non-tidal

| NAME           | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|----------------|--------------------|-----------------|----------------|
| NOT APPLICABLE |                    |                 |                |

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

| NAME           | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|----------------|--------------------|-----------------|----------------|
| NOT APPLICABLE |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs    ☐ Video coverage    ☐ Mapping

9. Samples taken.....NOT APPLICABLE.....

10. Investigation carried out by

☒ Foot    ☐ Boat    ☐ Aircraft

11. Remarks/Recommendation.....

REPAIRS HAS COMMENCED AND IT'S STILL  
ON GOING.

12. Time Investigation ended.....1300 HRS.....