

INCIDENT NUMBER - 3085135



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: **SADCO**

2. Type of Complaint/Incident:

☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution

☒ Others (Specify) **THREAT POINT INSTALLATION**

3. Incident Details

i. Date of Incident: **21/02/2022** ii. Date first reported: **22/02/2022**

iii. Date of first investigation: **16/03/2022**

iv. Date of follow-up investigation:

v. Time investigation started: **12:30 HOURS**

vi. Estimated quantity spilled: **None - Leak Point**

4. Site Details

i. Site/Location: **NEW 20" KOLLO CREEK - RUMI EKPE PL @ OKPOROKI, ANIBAMA**

ii. Position of Spill/Leak: **Point 1: N 07° 58' 14.4" E 006° 38' 19.7" Point 2: N 07° 58' 14.4" E 006° 38' 19.7"**

iii. Spill area

☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline

☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) **N/A**

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O'Clock

☐ 10 O'Clock

☐ 2 O'Clock

☐ 3 O'Clock

☐ 4 O'Clock

☐ 5 O'Clock

☐ 6 O'Clock

ii. Type of Oil Contaminant

☐ Crude Oil

☐ Condensate

☐ Chemicals

☐ Refined Products

☐ Others (Specify) **N/A**

iii. Facility

☒ Pipeline

☐ Flow Line

☐ Wellhead

☐ Manifold

☐ Flow Station

☐ Rig

☐ Storage Tank

☐ Compressor Plant

☐ Others (Specify)

iv. Cause of Spill

☐ Corrosion

☐ Equipment Failure

☒ Third Party Interference

☐ Accident

☐ Operational Error

☐ Others (Specify)

v. Visible Sign of Third Party Interference

☐ Hacksaw Marks

☐ Drilled Holes

☐ Blasting

☒ Theft

☐ Acid

☐ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify) N/A

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) N/A

iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW N/A

7. Extent of Impact

(a) Community (Indicate name)

- i.
 ii.
 iii.
 iv.

(b) Land (Indicate area in m²)

- i.
 ii.
 iii.
 iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

N/A

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation.....

SPSC should beef up
Security on its facility Right of
Way.

12. Time Investigation ended.....

15:45 HOURS

13. Name and Si