

INCIDENT NUMBER- 3085140



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident:

- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☒ Others (Specify) THREAT POINT INSTALLATION

3. Incident Details

- i. Date of Incident: 21/02/2022 ii. Date first reported: 22/02/2022
iii. Date of first investigation: 19/03/2022
iv. Date of follow-up investigation: _____
v. Time investigation started: 13:30 HOURS
vi. Estimated quantity spilled: N/A - Leak Point

4. Site Details

- i. Site/Location: OLD 20" KORO CREEK - RUMULEKPE PL @ OKPAROWO, ABIA STATE
ii. Position of Spill/Leak: N 04° 58' 16.0" E 006° 38' 32.5"
iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify) _____

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) N/A

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify) N/A

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify) _____

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident

- ☐ Operational Error ☐ Others (Specify) _____

v. Visible Sign of Third Party Interference

- ☐ Hack saw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (Specify) _____

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify) *N/A*

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) *N/A*

iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW *N/A*

7. Extent of Impact

(a) Community (Indicate name)

- i.
 ii.
 iii.
 iv.

(b) Land (Indicate area in m²)

- i.
 ii.
 iii.
 iv.

(c) Creek/Creek lets

☒ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☒ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☒ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☒ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.... N/A.....

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation..... SPDC should beef up
Security on its facility Right of
Way......

12. Time Investigation ended..... 15:00 HOURS.....

Signature of Participants