

INCIDENT NUMBER - 3085141



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident:

☐ Oil Pollution

☐ Fire/Explosion

☐ Drilling Mud/Chemical Pollution

☒ Others (Specify) WATER POINT INSTALLATION

3. Incident Details

i. Date of Incident: 21/02/2022

ii. Date first reported: 22/02/2022

iii. Date of first investigation: 22/03/2022

iv. Date of follow-up investigation:

v. Time investigation started: 15:35 HOURS

vi. Estimated quantity spilled: NON-LEAK POINT

4. Site Details

i. Site/Location: OLD 20" KOLA CREEK - RUMUKEPE PL @ OKOMATI, AHOAWESE, RS

ii. Position of Spill/Leak: N04° 58' 17.1" E006° 38' 40.7"

iii. Spill area

☒ Land

☐ Swamp

☐ Freshwater

☐ Mangrove

☐ Coastline

☐ Near shore

☐ Offshore

☐ Others (Specify)

iv. Structural Controls in Place

☐ Boom

☐ Trenches

☐ Bund Wall

☐ Sorbents

☐ Others (Specify) N/A

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O'Clock

☐ 10 O'Clock

☐ 2 O'Clock

☐ 3 O'Clock

☐ 4 O'Clock

☐ 5 O'Clock

☒ 6 O'Clock

ii. Type of Oil Contaminant

☐ Crude Oil

☐ Condensate

☐ Chemicals

☐ Refined Products

☐ Others (Specify) N/A

iii. Facility

☒ Pipeline

☐ Flow Line

☐ Wellhead

☐ Manifold

☐ Flow Station

☐ Rig

☐ Storage Tank

☐ Compressor Plant

☐ Others (Specify)

iv. Cause of Spill

☐ Corrosion

☐ Equipment Failure

☒ Third Party Interference

☐ Accident

☐ Operational Error

☐ Others (Specify)

v. Visible Sign of Third Party Interference

☐ Hacksaw Marks

☐ Drilled Holes

☐ Blasting

☒ Theft

☐ Acid

☐ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify) N/A

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) N/A

iii. Delineation of Impacted area

☐ Within Company's facility/ROW

☐ Outside Company's facility/ROW N/A

7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m²)

- i. i.
ii. ii.
iii. iii.
iv. iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... N/A

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation.....

SPDC should be eg up
Security on its facility Right of way.

12. Time Investigation ended..... 16:45 hours