



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: ADMAX PETROLEUM

2. Type of Complaint/Incident:

- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☒ Others (Specify) GASUOUS EMISSION

3. Incident Details

- i. Date of Incident: 02/09/2014 ii. Date first reported: 02/09/2014
iii. Date of first investigation: 04/09/2014
iv. Date of follow-up investigation: N/A
v. Time investigation started: 15:30 hrs
vi. Estimated quantity spilled:

4. Site Details

- i. Site/Location: 2" GAS FLOWLINE AT THE ROW CLOSE TO FLOWSTATION ON L124
ii. Position of Spill/Leak: NDS° 36° 9' 11" E 006° 48' 96.7'

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☒ Others (Specify) GAS

iii. Facility

- ☐ Pipeline ☒ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland
- ☐ Fish Pond
- ☐ Vegetation
- ☐ Fishing Net
- ☐ Surface water
- ☐ Venerable Objects
- ☐ Others (Specify)

ii. Nature of impact

- ☐ Oil stained vegetation
- ☐ Oil stained fishing nets
- ☐ Dead floating fishes
- ☐ Dead floating crabs
- ☐ Withering of vegetation
- ☐ Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW
- ☐ Outside Company's facility/ROW

7. Extent of Impact

- (a) Community (Indicate name)

i. 120m BE

ii. UGB EL6

iii.

iv.
- (b) Land (Indicate area in m²)

i.

ii.

iii.

iv.

- (c) Creek/Creek lets
- ☐ Tidal
- ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

- (d) Swamp
- ☐ Tidal
- ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

- (e) River
- ☐ Tidal
- ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

- (f) Shoreline/water
- ☐ Tidal
- ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. **Photograph/Map/Chart Ref.**

☒ Still photographs ☐ Video coverage ☐ Mapping

9. **Samples taken**..... *al/s*

10. **Investigation carried out by**

☒ Foot ☐ Boat ☐ Aircraft

11. **Remarks/Recommendation**.....

.....
.....

12. **Time investigation ended**.....

13. **Name and Signature of Participants**