



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: PPMC
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
i. Date of Incident: 06/08/14 ii. Date first reported: 06/08/14
iii. Date of first investigation: 13/08/14
iv. Date of follow-up investigation:.....
v. Time investigation started: 12:00 noon
vi. Estimated quantity spilled: little
4. Site Details
i. Site/Location: Km 49 Kurmin Idon Jos Area (Kajuru L.G.A)
ii. Position of Spill/Leak: N 037 6619° E 1133 970° 715m
iii. Spill area
☒ Land ☐ Swamp ☒ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
iv. Structural Controls in Place
☒ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
ii. Type of Oil contaminant
☐ Crude Oil ☐ Condensate ☐ Chemicals ☒ Refined Products (Pms)
☐ Others (specify).....
iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
iv. Cause Of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....
v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☒ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify).....

6. Impact of Incident

i. Properties impacted by the incident

☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify)

ii. Nature of impact

☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☒ Withering of vegetation ☐ Others

iii. Delineation of impacted area

☐ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

i. Kurnian Idon
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

i. 600 m²
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation *The impacted site should be clean up and remediated.*

12. Time investigation ended *12:30 pm*

13. Name and Signature of Participants

❖ NOSDRA

1. *ES1 Alsegu-O. Christopher*
2. *Titus Ahire & EO (GD)*
- 3.

Ch. Alsegu. 13/08/14
[Signature] 13/8/2014

❖ DPR

- 1.
- 2.
- 3.

❖ STATE MINISTRY OF ENVIRONMENT

- 1.
- 2.
- 3.

❖ LOCAL GOVERNMENT COUNCIL

- 1.
- 2.
- 3.

❖ COMPANY (PPMC) FIREMAN

1. *JAJA A-N Ash 13/08/14*
- 2.
- 3.

❖ COMMUNITY

- 1.
- 2.
- 3.