

Inc. No. 448/110



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident:

- ☒ Oil Pollution      ☐ Fire/Explosion      ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify) .....

3. Incident Details

- i. Date of Incident: 02/06/2022      ii. Date first reported: 03/06/2022  
iii. Date of first investigation: 06/06/2022  
iv. Date of follow-up investigation: .....  
v. Time investigation started: 12:55 Hrs  
vi. Estimated quantity spilled: nil - (slow leak)

4. Site Details

- i. Site/Location: 20" Runnel type - Nkporuba Trp @ Ibaa  
ii. Position of Spill/Leak: N 4.95335 E 6.84433  
iii. Spill area  
☒ Land      ☐ Swamp      ☐ Freshwater      ☐ Mangrove      ☐ Coastline  
☐ Near shore      ☐ Offshore      ☐ Others (Specify) .....  
iv. Structural Controls in Place  
☐ Boom      ☐ Trenches      ☐ Bund Wall      ☐ Sorbents      ☐ Others (Specify) nil

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock      ☐ 10 O'Clock      ☐ 2 O'Clock      ☐ 3 O'Clock  
☐ 4 O'Clock      ☐ 5 O'Clock      ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil      ☐ Condensate      ☐ Chemicals      ☐ Refined Products  
☐ Others (Specify) .....

iii. Facility

- ☒ Pipeline      ☐ Flow Line      ☐ Wellhead      ☐ Manifold      ☐ Flow Station      ☐ Rig  
☐ Storage Tank      ☐ Compressor Plant  
☐ Others (Specify) .....

iv. Cause of Spill

- ☐ Corrosion      ☐ Equipment Failure      ☒ Third Party Interference      ☐ Accident  
☐ Operational Error      ☐ Others (Specify) .....

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks      ☐ Drilled Holes      ☐ Blasting      ☒ Theft      ☐ Acid  
☐ Others (Specify) 4" Flange seen installed @ 12 o'clock

## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☐ Farmland   ☐ Fish Pond   ☐ Vegetation   ☐ Fishing Net   ☐ Surface water  
☐ Venerable Objects   ☐ Others (Specify) ..... *n/A*

### ii. Nature of impact

- ☐ Oil stained vegetation   ☐ Oil stained fishing nets   ☐ Dead floating fishes  
☐ Dead floating crabs   ☐ Withering of vegetation   ☐ Others (Specify) ..... *n/A*

### iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW   ☐ Outside Company's facility/ROW *n/A*

## 7. Extent of Impact

### (a) Community (Indicate name)

- i. ....  
ii. .... *n/A*  
iii. ....  
iv. ....

### (b) Land (Indicate area in m<sup>2</sup>)

- i. ....  
ii. .... *n/A*  
iii. ....  
iv. ....

### (c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (d) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (e) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (f) Shoreline/water

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs    ☐ Video coverage    ☐ Mapping

9. Samples taken..... *N/A*

10. Investigation carried out by

☒ Foot    ☐ Boat    ☐ Aircraft

11. Remarks/Recommendation.....

*there is need for increased security and surveillance. the ROW should be cleared of the vegetation.*

12. Time Investigation ended.....

*15:05 hrs*