

8. Photograph/Map/Chart list

☒ Still photographs

☐ Video coverage

☐ Mapping

9. Samples taken

N/A

10. Investigation carried out by

☒ Foot

☐ Horse

☐ Aircraft

11. Remarks/Recommendation

NATOC should clean up
the impaled area immediately

12. Time investigation ended 16:45 Hours

13. Name and Signature of Participants

Incident Number - 2022/LAR/063

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: **NAOC**

2. Type of Complaint/Incident:

☒ Oil Pollution

☐ Fire/Explosion

☐ Drilling Mud/Chemical Pollution

☒ Others (Specify) **CONDENSATE**

3. Incident Details

i. Date of Incident: **6/06/2022**

ii. Date first reported: **6/06/2022**

iii. Date of first investigation: **07/06/2022**

iv. Date of follow-up investigation:

v. Time investigation started: **14:20 HRS**

vi. Estimated quantity spilled: **6.92 bbls**

4. Site Details

i. Site/Location **OSTIE 1555 F/L @ OSTIE COMMUNITY, AKWELGA, RIVERS STATE**

ii. Position of Spill/Leak: **P1: N05°06'13.4" E006°28'58.5" P2: N05°06'13.4" E006°28'58.5" P3: N05°06'13.4" E006°28'58.5"**

iii. Spill area

☒ Land

☐ Swamp

☐ Freshwater

☐ Mangrove

☐ Coastline

☐ Near shore

☐ Offshore

☐ Others (Specify)

iv. Structural Controls in Place

☐ Boom

☒ Trenches

☐ Bund Wall

☐ Sorbents

☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☐ 12 O'Clock

☐ 10 O'Clock

☐ 2 O'Clock

☐ 3 O'Clock

☐ 4 O'Clock

☐ 5 O'Clock

☐ 6 O'Clock

ii. Type of Oil Contaminant

☐ Crude Oil

☒ Condensate

☐ Chemicals

☐ Refined Products

☐ Others (Specify)

iii. Facility

☐ Pipeline

☒ Flow Line

☐ Wellhead

☐ Manifold

☐ Flow Station

☐ Rig

☐ Storage Tank

☐ Compressor Plant

☐ Others (Specify)

iv. Cause of Spill

☐ Corrosion

☐ Equipment Failure

☐ Third Party Interference

☐ Accident

☐ Operational Error

☐ Others (Specify)

v. Visible Sign of Third Party Interference

☒ Hacksaw Marks

☐ Drilled Holes

☐ Blasting

☐ Theft

☐ Arson

☐ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the Incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface Water
☐ Venerable Object ☐ Others (Specify) N/A

ii. Nature of Impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fish
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) N/A

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicase name)

i. OSALE

(b) Land (Indicate area in m²)

i. 2466 m²

- ii. _____
 iii. _____
 iv. _____

(c) Creek/Creek lets

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK