



eni Naoc

POST CLEAN UP JOINT INSPECTION REPORT

1.	SPILL REF. NO.:	2014/LAR/227/2810		
2.	SPILL LOCATION:	OSHELE FLIT @ AKINIMA		
3.	CO-ORDINATES:	N 05° 06' 09.9" E 006° 28' 04.6"		
4.	DATE OF INSPECTION:	16-09-2015		
5.	SPILL DETAILS	DATE OF SPILL	CAUSE OF SPILL	QTY SPILLED
		22/01/14	EQUIPMENT FAILURE	21 BBLs
6.	DATE CLEAN UP COMMENCED:	18-06-2015		
7.	CONTRACTOR:	GLACIAS		
8.	CONTRACT NO.:			
9.	CLEAN UP METHOD:	MECHANICAL ☒	MANUAL ☒	OTHERS ☒
	IF OTHERS, SPECIFY			
10.	NO. OF INCINERATION PITS:	N/A	STATE OF BURIED PITS.	N/A
11.	CLEAN UP DURATION	DATE CLEAN UP COMPLETED	TOTAL DURATION OF CLEAN UP	
		26-06-2015	9 DAYS	
12.	ANY INCIDENT DURING CLEAN UP?	YES ☐	NO ☒	
	IF YES, WHAT TYPE			
13.	ANY CASUALTY/INJURY?	YES ☐	NO ☒	
	IF YES, HOW WAS IT MANAGED?			
14.	VISUAL OBSERVATIONS: (TICK AS APPROPRIATE)			
	ANY OIL SHEEN ON WATER?	YES ☐	NO ☒	NA ☐
	ANY OIL STAIN ON VEGETATION?	YES ☐	NO ☒	NA ☐
	IS SOIL WET WITH OIL?	YES ☐	NO ☒	NA ☐
	ANY PATCHES OF OIL ON IMPACTED AREA?	YES ☐	NO ☒	NA ☐
	IS DISPOSAL OF OIL DEBRIS SATISFACTORY?	YES ☒	NO ☐	NA ☐
	WAS DISPERSANT APPLIED?	YES ☐	NO ☒	NA ☐

14.	COMMUNITY ASSESSMENT:	VERY GOOD ☐	GOOD ☐	SATISFACTORY ☒	POOR ☐
15.	ANY SAMPLES COLLECTED?	YES ☒	NO ☐		
16.	IF YES, WHAT TYPE	SOIL ☒	WATER ☐		

17.	RECOMMENDATION:	Visual The site was properly
		Cleaned and the site passed. However the close
		Out of the site will be determined by the
		result of samples collected for laboratory
		analysis

18.	CONCLUSION (INDICATE WHETHER CLEAN UP IS CERTIFIED AS):	SATISFACTORILY ☒	NOT SATISFACTORY ☐	POOR ☐
-----	---	--	---	-------------------------------