



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY (NADCO) LTD.
2. Type of Complaint/Incident:
☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify).....
3. Incident Details
i. Date of Incident: 10/02/22 ii. Date first reported: 10/02/22
iii. Date of first investigation: 11/02/22 iv. Spill Incident No: 2022/SAR/006/022
v. Date of follow-up investigation: —/—/—
vi. Time investigation started: 1417 HRS
vii. Estimated quantity spilled(bbls): 20 viii. Quantity Recovered: NIL
4. Site Details
i. Site/Location: 18" TEBIDABA/BRASS P/L @ OYEREGBENE
ii. State: BAYELSA iii. L.G.A: SOUTHERN IJAW
iv. Spill Co-Ordinates: N(m) 04° 30' 17.4"
E(m) 006° 03' 24.7"
v. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify).....
iv. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify).....
iii. Facility
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
iv. Cause of Spill
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify).....
v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify).....



6. Impact of Incident

i. Properties impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
 ☒ Venerable Objects
 ☒ Others (specify) **NOT APPLICABLE**

ii. Nature of impact

- ☐ Oil stained vegetation
 ☐ Oil stained fishing nets
 ☐ Dead floating fishes
 ☐ Dead floating crabs
 ☐ Withering of vegetation
 ☒ Others **NOT APPLICABLE**

iii. Delineation of impacted area

- ☐ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops
 ☐ Fish Farm/ Pond
 ☐ Fishing Net
 ☐ Makeshift
 ☐ Permanent
 ☒ Others **NONE**

8. Extent of Impact

a) Community (indicate name)

i. **OYEREGBENE**

ii. _____

iii. _____

iv. _____

b) Land (indicate area in m²)

i. _____

ii. _____

iii. _____

iv. _____

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken..... NOT APPLICABLE

11. Investigation carried out by

☐ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation.....

.....

.....

13. Time investigation ended.....