



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: **NIGERIAN AIRP OIL COMPANY (NAOC)**
2. Type of Complaint/Incident:
☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify).....
3. Incident Details
i. Date of Incident: **17/06/2022** ii. Date first reported: **17/06/2022**
iii. Date of first investigation: **17/06/2022** Spill Incident No: **2022/LAR/069**
iv. Date of follow-up investigation:
v. Time investigation started: **15:09 HRS**
vi. Estimated quantity spilled (bbls): **3.01** viii. Quantity Recovered: **NIL**
4. Site Details
i. Site/Location: **6" THOMO - OGBONBIRI PPL @ AYAMASA**
ii. State: **BAYELSA** iii. L.G.A: **EKEREMOR**
iv. Spill Co-Ordinates: N(m). **05° 06' 39.9"**
E(m). **005° 54' 33.3"**
v. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify).....
vi. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock **(5-9 O' Clock)**
ii. Type of Oil contaminant
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify) **CONDENSATE**
iii. Facility
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....
iv. Cause of Spill
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify).....
v. Visible Sign of Third Party Interference
☒ Sacks Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify).....

6. Impact of Incident

i. Properties impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
☒ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
☒ Withering of vegetation
☒ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW
☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops
☒ Fish Farm/ Pond
☒ Fishing Net
☒ Makeshift
☒ Permanent
☒ Others

8. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m^2)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

10. Samples taken.....

11. Investigation carried out by

☒Foot

☒Boat

☒Aircraft

12. Remarks/Recommendation.....

13. Time investigation ended.....

14. Name and Signature of Participants

❖ NOSDRA

1. LIKAM WUEN Ekup ~~Signature~~ 17/06/2022
- 2.
- 3.

❖ DPR

- 1.
- 2.
- 3.

❖ STATE MINISTRY OF ENVIRONMENT

1. LUCKY JONES ~~Signature~~ 17/6/22
- 2.
- 3.

❖ COMPANY

1. Akporupo Festus. E. NAOC (HSE) ~~Signature~~
2. Eneke. O NAOC CMI ~~Signature~~
3. C. N. ADUWE NAOC SXO ~~Signature~~
- 4.
- 5.

❖ COMMUNITY

1. DUKE TARE, CDC chairman Ayamasg
- 2.
3. ~~Signature~~ ~~Signature~~
- 4.