



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY (NAOC)

2. Type of Complaint/Incident:

☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution  
☒ Others (Specify) CONDENSATE

3. Incident Details

i. Date of Incident: 16 / 06 / 2022 ii. Date first reported: 16 / 06 / 2022  
iii. Date of first investigation: 16 / 06 / 2022 iv. Spill Incident No: 2022/LAR/067  
v. Date of follow-up investigation: 14:47 HRS  
vi. Time investigation started: 14:47 HRS  
vii. Estimated quantity spilled(bbls): 9.2 viii. Quantity Recovered: NIL

4. Site Details

i. Site/Location: 6" TUOMO-DEBOINBIRI PPL @ AYAMASA  
ii. State: BAYELSA iii. L.G.A: EKEREMOR  
iv. Spill Co-Ordinates: N(m) 05° 06' 08.2"  
E(m) 005° 54' 38.6"

v. Spill area

☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline  
☒ Near shore ☒ Offshore ☒ Others (specify) .....

iv. Structural Controls in Place

☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify) .....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock  
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock (5-7 O'clock)

ii. Type of Oil contaminant

☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products  
☒ Others (specify) .....

iii. Facility

☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig  
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify) .....

iv. Cause of Spill

☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident  
☒ Operational Error ☒ Others (specify) .....

v. Visible Sign of Third Party Interference

☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid  
☒ Others (specify) .....



## 6. Impact of Incident

### i Properties impacted by the incident

- ☒ Farmland  
 ☒ Fish Pond  
 ☒ Vegetation  
 ☒ Fishing Net  
 ☒ Surface water  
☒ Venerable Objects  
 ☒ Others (specify).....

### ii. Nature of impact

- ☒ Oil stained vegetation  
 ☒ Oil stained fishing nets  
 ☒ Dead floating fishes  
☒ Dead floating crabs  
 ☒ Withering of vegetation  
 ☒ Others.....

### iii. Delineation of impacted area

- ☒ Within Company's facility/ROW  
 ☒ Outside Company's facility/ROW

## 7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops  
 ☒ Fish Farm/ Pond  
 ☒ Fishing Net  
 ☒ Makeshift  
☒ Permanent  
☒ Others .....

## 8. Extent of Impact

### a) Community (indicate name)

- i. ....  
 ii. ....  
 iii. ....  
 iv. ....

### b) Land (indicate area in m<sup>2</sup>)

- i. ....  
 ii. ....  
 iii. ....  
 iv. ....

### b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### c) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### d) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### e) Shoreline/water

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

9. Photograph/Map/Chart Ref.

☒ Still photographs    ☒ Video coverage    ☒ Mapping

10. Samples taken.....

11. Investigation carried out by

☒ Foot    ☒ Boat    ☒ Aircraft

12. Remarks/Recommendation - Delimitation Survey Completed.

- NAOC should intensify surveillances on her pipeline.
- NAOC should ensure best practice and operation during their production to avoid further environmental degr.

13. Time investigation ended.....

14. Name and Signature of Participants