

PHOTOGRAPHS TAKEN DURING THE JIV



PICTURE TAKEN AFTER THE EXCAVATION OF THE SPILLED POINT.



PICTURE TAKEN AFTER THE REPAIRS OF THE AFFECTED SPILLED POINT