



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This JIV Form is to be completed and signed by all participating parties in the field*

1. Company: NIGERIA AGRI OIL COMPANY LIMITED
2. Type of Complaint/Incident:  
☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution  
☒ Others (Specify) CONDENSATE
3. Incident Details  
i. Date of Incident: 26/09/2021 ii. Date first reported: 26/09/2021  
iii. Date of first investigation: 26/09/2021 iv. Spill Incident No.: 2021/LAR/097  
v. Date of follow-up investigation: N/A  
vi. Time investigation started: 1108 HRS  
vii. Estimated quantity spilled(bbls): 1,838 Bbls viii. Quantity Recovered: NOL
4. Site Details  
i. Site/Location: 6" TUOMO OGBOURBIRI PIPELINE AT ATAMASA  
ii. State: BAYELSA iii. L.G.A.: EKOROMOR  
iv. Spill Co-Ordinates: N(m): 05° 06' 58.2"  
E(m): 005° 54' 29.7"  
v. Spill area  
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline  
☒ Near shore ☒ Offshore ☒ Others (specify) SEASONAL SWAMP  
vi. Structural Controls in Place  
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify) .....
5. Circumstances Around Spill Point  
i. Visual observation of Hole Position  
☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock  
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock  
ii. Type of Oil contaminant  
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products  
☒ Others (specify) .....
- iii. Facility  
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig  
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify) .....
- iv. Cause of Spill  
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident  
☒ Operational Error ☒ Others (specify) SABOTAGE
- v. Visible Sign of Third Party Interference  
☒ Jacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid  
☒ Others (specify) 2" BALL VALVE WITH 2" PIPE CONNECTION  
INSTALLED ON THE FACILITY.



## 6. Impact of Incident

### i. Properties impacted by the incident

- ☒ Farmland  
 ☒ Fish Pond  
 ☒ Vegetation  
 ☒ Fishing Net  
 ☒ Surface water  
☒ Venerable Objects  
 ☒ Others (specify) .....

### ii. Nature of impact

- ☒ Oil stained vegetation  
 ☒ Oil stained fishing nets  
 ☒ Dead floating fishes  
☒ Dead floating crabs  
 ☒ Withering of vegetation  
 ☒ Others .....

### iii. Delineation of impacted area

- ☒ Within Company's facility ROW  
 ☒ Outside Company's facility/ROW

## 7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops  
 ☒ Fish Farm/ Pond  
 ☒ Fishing Net  
 ☒ Makeshift  
☒ Permanent  
☒ Others .....

## 8. Extent of Impact

### a) Community (indicate name)

- i. ....  
 ii. **AYAMASA**  
 iii. ....  
 iv. ....

### b) Land (indicate area in $m^2$ )

- i. ....  
 ii. **298.29  $m^2$**   
 iii. ....  
 iv. ....

### b) Creeks/Creek lets

- ☐ Tidal  
 ☐ Non-tidal

| NAME                                                                               | DIRECTION OF SLICK | LENGTH OF SLICK                                                                     | WIDTH OF SLICK |
|------------------------------------------------------------------------------------|--------------------|-------------------------------------------------------------------------------------|----------------|
|  | <b>N/A</b>         |  |                |

### c) Swamp

- ☐ Tidal  
 ☐ Non-tidal

| NAME                                                                                | DIRECTION OF SLICK | LENGTH OF SLICK                                                                      | WIDTH OF SLICK |
|-------------------------------------------------------------------------------------|--------------------|--------------------------------------------------------------------------------------|----------------|
|  | <b>N/A</b>         |  |                |

### d) River

- ☐ Tidal  
 ☐ Non-tidal

| NAME                                                                                | DIRECTION OF SLICK | LENGTH OF SLICK                                                                      | WIDTH OF SLICK |
|-------------------------------------------------------------------------------------|--------------------|--------------------------------------------------------------------------------------|----------------|
|  | <b>N/A</b>         |  |                |

### e) Shoreline/water

| NAME                                                                                | DIRECTION OF SLICK | LENGTH OF SLICK                                                                      | WIDTH OF SLICK |
|-------------------------------------------------------------------------------------|--------------------|--------------------------------------------------------------------------------------|----------------|
|  | <b>N/A</b>         |  |                |

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken N/A

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation CLEAN-UP OF THE IMPACTED AREA IS REQUIRED

13. Time investigation ended

14. Name and Signature of Participants

❖ NOSDRA

1. PROBLES KURUKUGHA IKOTI AP 26/09/2021  
2.  
3.

❖ DPR

1.  
2.  
3.

❖ STATE MINISTRY OF ENVIRONMENT

1.  
2.  
3.

❖ COMPANY

1. THEODORE OLIVER ADUOC THEO  
2.  
3. C.N. ADUOC NADOC SYD ADUOC  
4.  
5.

❖ COMMUNITY

1. ATAMASA  
2. OKOTI RIGHMAN BOMIEGHAN  
3. ABO  
4.  
5.