



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN ACUP OIL COMPANY
2. Type of Complaint/Incident:
☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify).....
3. Incident Details
i. Date of Incident: 14 / 12 / 21 ii. Date first reported: 14 / 12 / 2021
iii. Date of first investigation: 16 / 12 / 21 iv. Spill Incident No.: 2021/NH/LAR/046
v. Date of follow-up investigation:
vi. Time investigation started: 1216 HRS
vii. Estimated quantity spilled(bbls): NIL viii. Quantity Recovered: NIL
4. Site Details
i. Site/Location: 6" TUOMO- OGBOWBIRI PIPELINE AT
ii. State: BAYELSA iii. L.G.A.: EKPEREMOR
iv. Spill Co-Ordinates: N(m) 05° 06' 26.1"
E(m) 005° 54' 36.1"
v. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify) SEASONAL SWAMP
iv. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position 11 O'CLOCK
☒ 12 O' Clock ☐ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock
ii. Type of Oil contaminant
☐ Crude Oil ☐ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify) NON-LEAK
iii. Facility
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....
iv. Cause of Spill
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify).....
v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify) INSTALLED 3" BALL VALVE ON THE FACILITY

6. Impact of Incident

i. Properties impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
 ☒ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
 ☒ Withering of vegetation
 ☒ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops
 ☒ Fish Farm/ Pond
 ☒ Fishing Net
 ☒ Makeshift
☒ Permanent
☒ Others

8. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

AYAMASK


b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal


☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

c) Swamp

☐ Tidal


☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken... *NA*

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation.....

13. Time investigation ended... *14:20 HRS*

14. Name and Signature of Participants

❖ NOSDRA

1. *COBBLESS KUROKENHA IKO1* *[Signature]* *16-12-2021*
- 2.
- 3.

❖ DPR

1. *EKPENYON, EDEM* *[Signature]* *16/12/2021*
- 2.
- 3.

❖ STATE MINISTRY OF ENVIRONMENT

1. *TRUMAN JEPHTHAH* *[Signature]* *16-12-2021*
- 2.
- 3.

❖ COMPANY

1. *C.N. ADUWE* *NAOC STD* *[Signature]* *16/12/21*
2. *JOHN JAPHET* *NAOC HSE* *[Signature]* *16/12/21*
- 3.
- 4.
- 5.

❖ COMMUNITY

1. *OKO FI RATHMAN* *BOMIEHTON* *[Signature]* *16-12-21*
- 2.
- 3.
- 4.