



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This JIV Form is to be completed and signed by all participating parties in the field*

1. Company: NIGERIAN AGIP OIL COMPANY LTD
2. Type of Complaint/Incident:  
☒ Oil Pollution    ☒ Fire/Explosion    ☒ Drilling Mud/Chemical Pollution  
☒ Others (Specify).....
3. Incident Details  
i. Date of Incident: 09/02/2022 ii. Date first reported: 10/02/2022  
iii. Date of first investigation: 12/02/2022 iv. Spill Incident No: 2022/SAR/005  
v. Date of follow-up investigation: .....  
vi. Time investigation started: 10:50 AM  
vii. Estimated quantity spilled(bbls): 50 Ltrs viii. Quantity Recovered: NIL
4. Site Details  
i. Site/Location: 18" TEBBABA/BAXI PIPELINE AT LAGOS GBEKE  
ii. State: L.A. STATE iii. L.G.A: SOUTHERN IJAW  
iv. Spill Co-Ordinates: N(m) 04° 29' 21.8  
E(m) 006° 07' 48.8  
v. Spill area  
☒ Land    ☒ Swamp    ☒ Freshwater    ☒ Mangrove    ☒ Coastline  
☒ Near shore    ☒ Offshore    ☒ Others (specify).....  
iv. Structural Controls in Place  
☒ Boom    ☒ Trenches    ☒ Bund wall    ☒ Sorbents    ☒ Others (specify).....
5. Circumstances Around Spill Point  
i. Visual observation of Hole Position  
☒ 12 O' Clock    ☒ 10 O' Clock    ☒ 2 O' Clock    ☒ 3 O' Clock  
☒ 4 O' Clock    ☒ 5 O' Clock    ☒ 6 O' Clock  
ii. Type of Oil contaminant  
☒ Crude Oil    ☒ Condensate    ☒ Chemicals    ☒ Refined Products  
☒ Others (specify) .....
- iii. Facility  
☒ Pipeline    ☒ Flow line    ☒ Wellhead    ☒ Manifold    ☒ Flow Station    ☐ Rig  
☒ Storage Tank    ☒ Compressor Plant    ☒ Others (specify).....
- iv. Cause of Spill  
☒ Corrosion    ☒ Equipment Failure    ☒ Third Party Interference    ☒ Accident  
☒ Operational Error    ☒ Others (specify).....
- v. Visible Sign of Third Party Interference  
☒ Hacksaw Marks    ☒ Drilled Holes    ☒ Blasting    ☒ Theft    ☒ Acid  
☒ Others (specify).....

## 6. Impact of Incident

### i Properties impacted by the incident

- ☒ Farmland 
 ☒ Fish Pond 
 ☒ Vegetation 
 ☒ Fishing Net 
 ☒ Surface water 
 ☒ Venerable Objects 
 ☒ Others (specify).....

### ii. Nature of impact

- ☒ Oil stained vegetation 
 ☒ Oil stained fishing nets 
 ☒ Dead floating fishes 
 ☒ Dead floating crabs 
 ☒ Withering of vegetation 
 ☒ Others.....

### iii. Delineation of impacted area

- ☐ Within Company's facility/ROW 
 ☒ Outside Company's facility/ROW

## 7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops 
 ☒ Fish Farm/ Pond 
 ☒ Fishing Net 
 ☒ Makeshift 
 ☒ Permanent 
 ☒ Others .....

## 8. Extent of Impact

### a) Community (indicate name)

- i. LAGOS GREENE  
 ii. ....  
 iii. ....  
 iv. ....

### b) Land (indicate area in m<sup>2</sup>)

- i. 778,47 m<sup>2</sup>  
 ii. ....  
 iii. ....  
 iv. ....

### b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### c) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### d) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### e) Shoreline/water

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken..... *nil*

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation *CLEANING OF THE IMPACTED AREA  
THE COMPANY RIGHT OF WAY SHOULD BE CLEAR  
TIN REPAIRS/DELIMITATION SURVEY COMPLETED*

13. Time investigation ended..... *15:45 PM*

14. Name and Signature of Participants

❖ NOSDRA

1. *UKAM WON E*
- 2.
- 3.

*12-02-2022*

❖ DPR

- 1.
- 2.
- 3.

❖ STATE MINISTRY OF ENVIRONMENT

1. *HOWLAND IBERU*
- 2.
- 3.

*12/02/2022*

❖ COMPANY

1. *Ejoagu Charles NAOE CRV* *12/02/2022*
2. *OMONGO MIKE NAOE HSE* *12/2/2022*
3. *Omorguon Eddy Surveyor* *12/2/2022*
- 4.