



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JIV INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY LTD
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify):
3. Incident Details:
i. Date of Incident: 07/07/2021 ii. Date first reported: 07/07/2021
iii. Date of first investigation: 07/07/2021 iv. Spill Incident No: 2021/SAR/006
v. Date of Follow-up investigation:
vi. Time investigation started: 11:14 AM
vii. Estimated quantity spilled (bbls): Nil viii. Quantity Recovered: Nil
4. Site Details:
i. Site Location: 18' CEBISABA/BRASS PIPELINE AT MBIKIBA
ii. State: BAYELSA iii. L.G.A: SOUTHERN IJAW
iv. Spill Coordinates: N(m) 04° 29' 08.5"
E(m) 006° 25' 45.9"
v. Spill at:
☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near-shore ☐ Offshore ☐ Others (specify):
- iv. Structures/Obstacles in Place
☐ Buoys ☐ Bund wall ☐ Sorbents ☐ Others (specify):
5. Circumstances of Spill Point:
i. Visual orientation of Hole Position
☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
ii. Type of Spill:
☒ Gas ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify):
iii. Facility:
☒ Pipeline ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify):
iv. Cause of Spill:
☐ Operator Error ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Others (specify):
v. Visible Signs of Third Party Interference:
☐ Illegal Drilling Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (specify):



6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing Net ☐ Makeshift
☐ Permanent ☐ Others

8. Extent of Impact

a) Community (indicate name)

- i. MBIKWA
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken..... *NOL*

11. Investigation carried out by

☐ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation *THERE WAS NO TRACE OR SPORES OF CRUDE OR ASH? PORE OF JIV. HENCE NO CLEAN-UP IS REQUIRE AROUND THE AREA.*

13. Time investigation ended *13:56pm*

14. Name and Signature of Participants

❖ NOSDRA

1. *Ukram, IBON EKUP*

2.

3.

[Signature] 07/07/2021

❖ DPR

1.

2.

3.

❖ STATE MINISTRY OF ENVIRONMENT

1. *ROWLAND IBERU*

2.

3.

[Signature] 07/07/2021

❖ COMPANY

1. *AGRAKWURIBE Emma NAOCAN*

2. *OMONGO MIKE NAOC HSE*

3. *MUDEMA ODIGHIOYE SURVEYOR*

4.

5.

[Signature] 07/07/21
[Signature] 7/7/2021
[Signature] 7/7/2021