

## APPENDIX A

PHOTOGRAPHS TAKEN DURING A JOINT INVESTIGATION VISIT TO  
6" AZUZUAMA/TEBIDABA 2TB PIPELINE AT IKEBIRI, SOUTHERN  
IJAW LOCAL GOVERNMENT AREA, BAYELSA STATE.



PICTURE 1: SHOWING 3" FLANGE INSTALLED AT THE INCIDENT POINT BY UNKNOWN PERSONS FOR CRUDE OIL THEFT.



PICTURE 2: SHOWING REPAIRED AND WRAPPED SECTION OF THE PIPELINE.