

APPENDIX A

PHOTOGRAPHS TAKEN DURING A JOINT INVESTIGATION VISIT TO 6" AZUZUAMA/TEBIDABA 2TB PIPELINE AT IKEBIRI, SOUTHERN IJAW LOCAL GOVERNMENT AREA, BAYELSA STATE.



PICTURE 1: SHOWING 2" VALVE INSTALLED AT 12 O' CLOCK POSITION BY UNKNOWN PERSON FOR CRUDE OIL THEFT.



PICTURE 2: SHOWING CRUDE OIL IMPACT FROM THE INSTALLED VALVE.