



# **NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**

## **JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This JIV Form is to be completed and signed by all participating parties in the field*

1. Company: **NIGERIAN AGIP OIL COMPANY [NAOC]**

2. Type of Complaint/Incident:

☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution

☒ Others (Specify).....

3. Incident Details

i. Date of Incident: **01/11/2022** ii. Date first reported: **01/11/2022**

iii. Date of first investigation: **02/11/2022** iv. Spill Incident No: **2022/SAN/129**

v. Date of follow-up investigation: .....

vi. Time investigation started: **14:42 HRS**

vii. Estimated quantity spilled(bbls): **6** viii. Quantity Recovered: **2**

4. Site Details

i. Site/Location: **18" OBAMA/BRASS P/L AT GOLOBOKIRI**

ii. State: **BAYELSA** iii. L.G.A: **MEMBE**

iv. Spill Co-Ordinates: N(m) **04° 29' 59.6"**  
E(m) **006° 15' 25.8"**

v. Spill area

☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline

☒ Near shore ☒ Offshore ☒ Others (specify).....

iv. Structural Controls in Place

☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock

☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock

ii. Type of Oil contaminant

☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products

☒ Others (specify) .....

iii. Facility

☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig

☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....

iv. Cause of Spill

☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident

☒ Operational Error ☒ Others (specify).....

v. Visible Sign of Third Party Interference

☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid

☒ Others (specify) **INSTALLED 3" VALVE**

## 6. Impact of Incident

### i Properties impacted by the incident

- ☒ Farmland  
 ☒ Fish Pond  
 ☒ Vegetation  
 ☒ Fishing Net  
 ☒ Surface water  
☒ Venerable Objects  
 ☒ Others (specify).....

### ii. Nature of impact

- ☒ Oil stained vegetation  
 ☒ Oil stained fishing nets  
 ☒ Dead floating fishes  
☒ Dead floating crabs  
 ☒ Withering of vegetation  
 ☒ Others.....

### iii. Delineation of impacted area

- ☒ Within Company's facility/ROW  
 ☒ Outside Company's facility/ROW

## 7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops  
 ☒ Fish Farm/ Pond  
 ☒ Fishing Net  
 ☒ Makeshift  
☒ Permanent  
☒ Others .....

## 8. Extent of Impact

### a) Community (indicate name)

- i. GOLUBOKIRI  
 ii. //  
 iii. //  
 iv. //

### b) Land (indicate area in m<sup>2</sup>)

- i. 6601.250  
 ii. //  
 iii. //  
 iv. //

### b) Creeks/Creek lets

☒ Tidal

☒ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    | N/A             |                |

### c) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    | N/A             |                |

### d) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    | N/A             |                |

### e) Shoreline/water

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    | N/A             |                |

9. Photograph/Map/Chart Ref.

☒ Still photographs

☒ Video coverage

☒ Mapping

10. Samples taken..... N/A

11. Investigation carried out by

☒ Foot

☒ Boat

☒ Aircraft

12. Remarks/Recommendation..... NAOC SHOULD INTENSIFIED  
SURVEILLANCE AND ALSO CLEAN UP THE IMPACTED  
ENVIRONMENT IMMEDIATELY -

13. Time investigation ended..... 17:09 HRS

Signature of Participants