

APPENDIX A

PICTURES TAKEN DURING THE JOINT INVESTIGATION VISIT AT 18" TEBIDABA/BRASS PIPELINE AT LAGOSGBENE, SOUTHERN IJAW LOCAL GOVERNMENT, BAYELSA STATE.



PICTURE 1 FROM THE LEFT: 2" VALVE INSTALLED AT 12 O' CLOCK POSITION OF THE PIPEPELINE BY UNKNOWN PERSON(S) FOR CRUDE OIL THEFT.

PICTURE 2: INCIDENT POINT AFTER REPAIR AND AQUA WRAPPING.