

APPENDIX A

PICTURES TAKEN DURING THE JOINT INVESTIGATION VISIT AT 18" TEBIDABA/BRASS PIPELINE AT MBIKIBA, SOUTHERN IJAW LOCAL GOVERNMENT, BAYELSA STATE.



PICTURE 1 FROM THE LEFT: SHOWING 3" VALVE INSTALLED AT 12 O' CLOCK POSITION OF THE PIPELINE BY UNKNOWN PERSON (S) FOR CRUDE OIL THEFT.

PICTURE 2: SHOWING THE INCIDENT POINT AFTER REPAIR.