



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Mobil Producing Nigeria -MPN	
Reporting Officer		Mike McAdie	
Designation		General Manager, Joint Venture Operations	
Phone Number		0817 206 8193	
Email Address		mike.mcadie@exxonmobil.com	
Incident Number		20 / 2022	
Section 2 - Location			
State / LGA		Yoho PP OML 104 - /	
Coordinates of spill		EASTINGS 4Deg 9Min/26Secs N NORTHINGS 7Deg 29Min/33Secs E	
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		11/8/2022 Time: 14:00 hours local time	
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....	
Cause of spill		Other: At about 1400hrs, silvery sheen was observed at north side of Yoho YP. Sheen was traced to produce water treatment system (WEMCO) overboard water outlet due to LP separator oily water.	
Status of spill		☒ Contained ☐ Not Contained ☐ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others (specify): Oily water source, LP Separator produced water outlet line isolated and sheen eliminated.	
Product Data	☐ Persistent		☐ Non Persistent
	Product Name/Type		
	SG/API Gravity		
	Pour Point		
	Wax Content		

	Asphaltene		
	Sulphur Content		
	Viscosity		
Oil	Slick Locations(s)		

observation	Slick Dimension(s)		
	Orientation of slick(s)		
	Distribution of oil		
	Obvious odour		
Oil descriptions	Tarballs (tb)		
	Convergence line (co)		
	No structure (ns)		
	Windrows (wr)		
	Streamers (st)		
	Patches (pa)		
Oil color and appearance	Silver/grey		
	Rainbow		
	Metallic		
	Transitional		
	Dark		
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat ☐ On site ☐ Others.....	

Section 4 – Approximate Duration

Release Rate	Instantaneous Release		Continuous Release	
		Per Hour	☐ Hours	☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.01022bbl of Oily Water based on sheen appearance		
	Coverage	About 500m x 50m of 70% barely discernible and 30% silvery sheen on sea water		
	Direction of travel			

Section 5 - Weather

METEOROLOGICAL DATA		NIMET weather forecast
Wind Direction (wind direction given from)	North West	
Initial Wind Speed	0.61 knots	
Air Temperature (C or OF)		
Visibility Estimate	☐ Good ☐ Fair ☐ Poor	
OCEANOGRAPHIC DATA		
Water Current Speed		
Tide Phase: Flood	High ☐ Ebb ☐	
Water Temperature (OC or OF)		
High Tide Time		
Source		

Section 6 – Pre-Entry Activities

Mechanical cleaning	Yes ☐	No ☒
Recovery of free phase oil	Yes ☐	No ☒
Booming	Yes ☐	No ☒
Wild life rehabilitation	Yes ☐	No ☒
Dispersant application	Yes ☐	No ☒

Section 6 – Pre-Entry Activities

