

INCIDENT NUMBER - 589089



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC
2. Type of Complaint/Incident:
- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
- ☒ Others (Specify) WRFI POINT INSTALLATION
3. Incident Details
- i. Date of Incident: 24/08/2022 ii. Date first reported: 25/08/2022
- iii. Date of first investigation: 12/12/2022
- iv. Date of follow-up investigation:
- v. Time investigation started: 14:02 HOURS
- vi. Estimated quantity spilled: NON - LEAK POINT
4. Site Details
- i. Site/Location: 14th Okorafia - Rumuekpe Plk at Ula-Okobo
- ii. Position of Spill/Leak: N5 0627 22 E 6 572025
- iii. Spill area
- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
- ☐ Near shore ☐ Offshore ☐ Others (Specify)
- iv. Structural Controls in Place
- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) N/A
5. Circumstances Around Spill Point
- i. Visual observation of Hole Position
- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
- ☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock
- ii. Type of Oil Contaminant
- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
- ☐ Others (Specify) N/A
- iii. Facility
- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
- ☐ Storage Tank ☐ Compressor Plant
- ☐ Others (Specify)
- iv. Cause of Spill
- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
- ☐ Operational Error ☐ Others (Specify)
- v. Visible Sign of Third Party Interference
- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
- ☐ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify) **N/A**

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) **N/A**

iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW **N/A**

7. Extent of Impact

(a) Community (Indicate name)

i. **ULA - OKOBO**

ii.

iii.

iv.

(b) Land (Indicate area in m²)

i. **NON - LEAK**

ii.

iii.

iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... *N/A*

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation.....

SPDC should beef up security on its frontier right of way

12. Time Investigation ended.....

16:30 HRS