



## NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

### JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NADC

#### 2. Type of Complaint/Incident:

- ☒ Oil Pollution    ☐ Fire/Explosion    ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify) .....

#### 3. Incident Details

- i. Date of Incident: 27/02/2023    ii. Date first reported: 27/02/2023  
iii. Date of first investigation: 27/02/2023  
iv. Date of follow-up investigation: NOT APPLICABLE  
v. Time investigation started: 14 00 HRS  
vi. Estimated quantity spilled: 5 BARRELS

#### 4. Site Details

- i. Site/Location: 18" EOC-DGODA PIPELINE AT DWUBS  
ii. Position of Spill/Leak: N 05° 12' 03.7" E 006° 35' 24.8"  
iii. Spill area  
☒ Land    ☐ Swamp    ☐ Freshwater    ☐ Mangrove    ☐ Coastline  
☐ Near shore    ☐ Offshore    ☐ Others (Specify) .....

#### iv. Structural Controls in Place

- ☐ Boom    ☐ Trenches    ☐ Bund Wall    ☐ Sorbents    ☐ Others (Specify) NOT APPLICABLE

#### 5. Circumstances Around Spill Point

##### i. Visual observation of Hole Position

- ☐ 12 0'Clock    ☐ 10 0'Clock    ☐ 2 0'Clock    ☐ 3 0'Clock  
☐ 4 0'Clock    ☐ 5 0'Clock    ☐ 6 0'Clock    1-3 0'Clock

##### ii. Type of Oil Contaminant

- ☒ Crude Oil    ☐ Condensate    ☐ Chemicals    ☐ Refined Products  
☐ Others (Specify) .....

##### iii. Facility

- ☒ Pipeline    ☐ Flow Line    ☐ Wellhead    ☐ Manifold    ☐ Flow Station    ☐ Rig  
☐ Storage Tank    ☐ Compressor Plant  
☐ Others (Specify) .....

##### iv. Cause of Spill

- ☐ Corrosion    ☐ Equipment Failure    ☒ Third Party Interference    ☐ Accident  
☐ Operational Error    ☐ Others (Specify) .....

##### v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks    ☐ Drilled Holes    ☐ Blasting    ☐ Theft    ☐ Acid  
☐ Others (Specify) .....

## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☐ Farmland
 ☐ Fish Pond
 ☒ Vegetation
 ☐ Fishing Net
 ☐ Surface water  
☐ Venerable Objects
 ☐ Others (Specify) .....

### ii. Nature of impact

- ☒ Oil stained vegetation
 ☐ Oil stained fishing nets
 ☐ Dead floating fishes  
 Dead floating crabs
 Withering of vegetation
 Others (Specify) .....

### iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

## 7. Extent of Impact

### (a) Community (Indicate name)

i. DIKUBE

ii. ....

iii. ....

iv. ....

### (b) Land (Indicate area in m<sup>2</sup>)

i. 56.08 m<sup>2</sup>

ii. ....

iii. ....

iv. ....

### (c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (d) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (e) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (f) Shoreline/water

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs   ☐ Video coverage   ☐ Mapping

9. Samples taken.....NOT APPLICABLE.....

10. Investigation carried out by

☒ Foot   ☐ Boat   ☐ Aircraft

11. Remarks/Recommendation.....NAADC SHOULD COMPLETE THE  
REPAIR OF THE AFFECTED PIPELINE AND  
CLEAN UP THE AREA IMPACTED BY THE SPILL.

12. Time Investigation ended.....1626 HRS.....