



2023/LAR/043

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIA AGIP OIL COMPANY

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....

3. Incident Details

- i. Date of Incident: 25/01/2023 ii. Date first reported: 25/01/2023
iii. Date of first investigation: 25/01/2023
iv. Date of follow-up investigation: N/A
v. Time investigation started: 1530hrs
vi. Estimated quantity spilled: 7.84 BLS

4. Site Details

- i. Site/Location: 24th DEWDA/RATES P/L @ OROODH, ANKLESA
ii. Position of Spill/Leak: N04 01' 06.1" E 006 32' 05.4" R/S
iii. Spill area
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock

ii. Type of Oil contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify).....

iii. Facility

- ☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....

iv. Cause Of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (specify).....

8. Photograph/Map/Chart Ref.

☒ Still photographs

☐ Video coverage

☒ Mapping

9. Samples taken... *N/A*

10. Investigation carried out by

☒ Foot

☐ Boat

☐ Aircraft

11. Remarks/Recommendation

NADC should intensify surveillance and carry out repairs as soon as possible. Clean up the impacted as well.

12. Time Investigation ended... *1620hrs*

13. Name and Signature of Participants

❖ NOSDRA

1. *Amadi Eagle Alexander Eagle 25/1/2023*
2.
3.

❖ NUPRC/NMDPRA

1.
2.
3.

❖ STATE MINISTRY OF ENVIRONMENT

1. *EBIANGA DAPPA Ebanga 25/01/2023*
2.
3.

❖ LOCAL GOVERNMENT COUNCIL

1.
2.
3.

❖ COMPANY

1. *AKPO - SAC ONI 25/01/2023*
2. *AKPE CHRISTIAN Akpe 25/01/2023*
3.

❖ COMMUNITY

1. *Pst. Mathias Emeike Amufuwa 25/01/2023*
2.
3.

6. Impact of Incident

i Properties impacted by the incident

☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water

☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes

☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

: ARDA + Co. L.

b) Land (indicate area in m²)