



2023/LAR/115

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NAOC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify) _____

3. Incident Details

- i. Date of Incident: 10/04/2023 ii. Date first reported: 10/04/2023
iii. Date of first investigation: 10/04/2023
iv. Date of follow-up investigation: _____
v. Time investigation started: 1239 Hrs
vi. Estimated quantity spilled: 3 BARRELS

4. Site Details

- i. Site/Location: 18" EBOCHA-OGODA PIPELINE AT UBETA
ii. Position of Spill/Leak: N05°16'56.6" E006°35'36.3"

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify) _____

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☒ Bund Wall ☐ Sorbents ☐ Others (Specify) _____

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 1 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock ☒ 10-11 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify) _____

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify) _____

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify) _____

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify) _____

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify)

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
 Dead floating crabs Withering of vegetation Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. UBETA

(b) Land (Indicate area in m²)

i. 20000 m²

- ii.
 iii.
 iv.

(c) Creek/Creek lets

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT APPLICABLE			

(d) Swamp

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT APPLICABLE			

(e) River

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT APPLICABLE			

(f) Shoreline/water

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT APPLICABLE			

Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... NOT APPLICABLE

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation..... REPAIRS HAS BEEN COMPLETED.
CLEAN-UP OF THE IMPACTED AREA TO COMMENCE
AS SOON AS PRACTICABLY POSSIBLE.

Time Investigation ended.....

Name and Signature of Participants