




National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		NPSC/NAIPCL	
Site Location Name		JEGUN-IMOLEN SHUTTLE KASIMU	
Reporting Officer		FRM SPT HSE SHUTTLE KASIMU	
Designation		SPT HSE	
Phone Number		08069297020	
Email Address		kasimu.shuttle@npscgroup.com	
Incident Number		NPSC/MOS/02-23	
Section 2 – Location			
State/ LGA		LAGOS/ ARIUNO - ODOFIN	
Coordinates of spill			
		☐ Inland ☐ River ☐ Mangrove ☒ Shoreline ☐ Port ☐ Harbour ☐ Offshore ☐ Subsea ☐ Swamp Area ☐ Others	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		15/03/2023	
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tanker/Ship ☐ Tank Truck ☐ Barge ☒ Tanker Vessel ☒ Pipeline PIPELINE (Specify pipeline diameter.....) ☐ Trunkline ☒ Flowline ☐ Bulkline ☐ Delivery line ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....	
Cause of spill		THIRD PARTY INTERFERENCE	
Status of spill		☒ Contained ☒ Not Contained ☐ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others (specify) Petrosol	
Product Data	☐ Persistent		☐ Non Persistent
	Product Name/Type	NOT APPLICABLE	
	SG/API Gravity		
	Pour Point		
	Wax Content		
	Asphaltene		
	Sulphur Content		
Viscosity			



CES (HSE)
PLS treat

AGCS (Badm)
PLS treat
3/3/23

Oil observation	Slick location(s)	
	Slick Dimension(s)	
	Orientation of slick(s)	
	Distribution of oil	
	Obvious odour	
Oil descriptions	Tarballs (tb)	
	Convergence line (co)	
	No structure (ns)	
	Windrows (wr)	
	Streamers (st)	
	Patches (pa)	
Oil color and appearance	Silver/grey	
	Rainbow	
	Metallic	
	Transitional	
	Dark	
	Mousse	
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat ☒ On site ☐ Others.....

Section 4 - Approximate Duration

Release Rate	Instantaneous Release	Continuous Release		
		Per hour	☐ Hours	☐ Days
Description of observed spill	Estimated Quantity (bbl)	NOT-LET QUANTIFIED		
	Coverage			
	Direction of travel			

Section 5 - Weather

METEOROLOGICAL DATA		NOT APPLICABLE	NIMET weather forecast
Wind Direction (wind direction given from)			
Initial Wind Speed			
Air Temperature (°C or °F)			
Visibility Estimate	☐ Good ☐ Fair ☐ Poor		
OCEANOGRAPHIC DATA		NOT APPLICABLE	
Water Current Speed			
Tide Phase: Flood	High ☐	Ebb ☐	
Water Temperature (°C or °F)			
High Tide Time			
Source			

Section 6 - Pre-Entry Activities

Mechanical cleaning	Yes ☐	No ☐
Recovery of free phase oil	Yes ☐	No ☐
Booming	Yes ☐	No ☐
Wild life rehabilitation	Yes ☐	No ☐
Dispersant application	Yes ☒	No ☐

Section 7 - Oil Spill Model Request

Spill Modeling?	Trajectory	Surface 2D ☐	Sub-surface 3D ☐	Not at this time ☐
Additional information (please use start date and time including still photographs)				
Spill from the pipeline has been contained				

Section 8- Equipment	
On Site	

REPORTING OFFICER: SAHITHI, K

DESIGNATION: f Supt ASE

SIGNATURE: 

DATE: 15/03/23

*RBA Report must be submitted within 24 Hours of the Spill Incidence.