



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		NNPC/NPSC DEPOT, MOSIMI	
Site Location Name		MOSIMI DEPOT	
Reporting Officer		S HITH, KASIMU	
Designation		for: SUPPLY HSE	
Phone Number		08069297020	
Email Address		alqasims@yahoo.com	
Incident Number		NPSC/MOS/01-23	
Section 2 – Location			
State/ LGA		OGUN / SAGAMU LOCAL GOVT.	
Coordinates of spill			
		☒ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☐ Offshore ☐ Subsea ☐ Swamp Area ☐ Others	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		27.01.2023	
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tanker/Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline NOT YET ASCERTAINED	
		PIPELINE (Specify pipeline diameter.....) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Delivery line ☐ Export line ☐ Gas Line.	
		STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify).....	
		PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....	
Cause of spill		NOT YET ASCERTAINED	
Status of spill		☐ Contained ☐ Not Contained ☐ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☐ Others (specify).....	
Product Data	☒ Persistent		☐ Non Persistent
	Product Name/Type		
	SG/API Gravity		
	Pour Point		
	Wax Content		
	Asphaltene		
	Sulphur Content		
Viscosity			

Oil observation	Slick location(s)			
	Slick Dimension(s)			
	Orientation of slick(s)			
	Distribution of oil			
	Obvious odour			
Oil descriptions	Tarballs (tb)			
	Convergence line (co)			
	No structure (ns)			
	Windrows (wr)			
	Streamers (st)			
Oil color and appearance	Patches (pa)			
	Silver/grey			
	Rainbow			
	Metallic			
	Transitional			
	Dark			
	Mousse			
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat ☐ On site ☐ Others.....		
Section 4 - Approximate Duration				
Release Rate	Instantaneous Release		Continuous Release	
	NOT YET DETERMINED		Per hour	☐ Hours ☐ Days
Description of observed spill	Estimated Quantity (bbl)			
	Coverage			
	Direction of travel			
Section 5 - Weather				
METEOROLOGICAL DATA				NIMET weather forecast
Wind Direction (wind direction given from)		NOT APPLICABLE		
Initial Wind Speed				
Air Temperature (°C or °F)				
Visibility Estimate		☐ Good ☐ Fair ☐ Poor		
OCEANOGRAPHIC DATA				
Water Current Speed		NOT APPLICABLE		
Tide Phase: Flood		High ☐ Ebb ☐		
Water Temperature (°C or °F)				
High Tide Time				
Source				
Section 6 - Pre-Entry Activities				
Mechanical cleaning	Yes ☒	No ☐		
Recovery of free phase oil	Yes ☐	No ☐		
Booming	Yes ☐	No ☐		
Wild life rehabilitation	Yes ☐	No ☐		
Dispersant application	Yes ☒	No ☐		
Section 7 - Oil Spill Model Request				

Spill Modeling?	Trajectory	Surface 2D ☐	Sub-surface 3D ☐	Not at this time ☐
Additional information (please use start date and time including still photographs)				
- UNDERGROUND WATER CONTAMINATION AND POLLUTION OF TANK 61 WATER. - TANK CLEANING WAS CARRIED OUT AND CONTAMINATED BUSHHOLES WERE DECOMMISSIONED				

Section 8- Equipment	
On Site	

REPORTING OFFICER: STHIV, K

DESIGNATION: for: Supr HSE

SIGNATURE: [Signature] 24/03/23 DATE: 24/03/23

*RBA Report must be submitted within 24 Hours of the Spill Incidence.