



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident:

- ☐ Oil Pollution
 ☐ Fire/Explosion
 ☐ Drilling Mud/Chemical Pollution
 ☒ Others (Specify) ILLEGAL CONNECTION

3. Incident Details

- i. Date of Incident: 05/07/2023
 ii. Date first reported: 05/07/2023
 iii. Date of first investigation: 13/07/2023
 iv. Date of follow-up investigation: NOT APPLICABLE
 v. Time investigation started: 1405 HRS
 vi. Estimated quantity spilled: NOT APPLICABLE

4. Site Details

- i. Site/Location: 4" OBELLE - IBAA DELIVERY LINE AT IBAA
 ii. Position of Spill/Leak: N 04° 59' 19.907" E 006° 28' 23.566"

iii. Spill area

- ☐ Land
 ☐ Swamp
 ☐ Freshwater
 ☐ Mangrove
 ☐ Coastline
☐ Near shore
 ☐ Offshore
 ☒ Others (Specify) NDN - LEAKING

iv. Structural Controls in Place

- ☐ Boom
 ☐ Trenches
 ☐ Bund Wall
 ☐ Sorbents
 ☒ Others (Specify) NOT APPLICABLE

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock
 ☐ 10 O'Clock
 ☐ 2 O'Clock
 ☐ 3 O'Clock
☐ 4 O'Clock
 ☐ 5 O'Clock
 ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☐ Crude Oil
 ☐ Condensate
 ☐ Chemicals
 ☐ Refined Products
☒ Others (Specify) NDN - LEAKING

iii. Facility

- ☐ Pipeline
 ☐ Flow Line
 ☐ Wellhead
 ☐ Manifold
 ☐ Flow Station
 ☐ Rig
☐ Storage Tank
 ☐ Compressor Plant
☒ Others (Specify) DELIVERY LINE

iv. Cause of Spill

- ☐ Corrosion
 ☐ Equipment Failure
 ☒ Third Party Interference
 ☐ Accident
☐ Operational Error
 ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks
 ☐ Drilled Holes
 ☐ Blasting
 ☐ Theft
 ☐ Acid
☐ Others (Specify) INSTALLED 2" FLANGE

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☒ Others (Specify) *NOI - LEAKING*

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
 Dead floating crabs Withering of vegetation ☒ Others (Specify) *NOI - LEAKING*

iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

NOT APPLICABLE

(a) Community (Indicate name)

(b) Land (Indicate area in m²)

- i. i.
 ii. ii.
 iii. iii.
 iv. iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... NOT APPLICABLE

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

REPAIR OF THE

11. Remarks/Recommendation..... SPDC SHOULD COMPLETE THE
AFFECTED SECTION OF THE DELIVERY LINE. SPDC SHOULD
INCREASE SURVEILLANCE ALONG THE FACILITY.

12. Time Investigation ended..... 1437 HRS