



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: S.P.D.C

2. Type of Complaint/Incident:

- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☒ Others (Specify) ILLEGAL CONNECTION

3. Incident Details

- i. Date of Incident: 08/07/2023 ii. Date first reported: 08/07/2023
iii. Date of first investigation: 21/07/2023
iv. Date of follow-up investigation: NOT APPLICABLE
v. Time investigation started: 1561 HRS
vi. Estimated quantity spilled: NOT APPLICABLE

4. Site Details

- i. Site/Location: 36" RUMUZEKPE - MKPOICH PIPELINE AT IBAA
ii. Position of Spill/Leak: N 04° 57' 14.652" E 006° 48' 55.440"

iii. Spill area

- ☐ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☒ Others (Specify) NON-LEAKING

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☒ Others (Specify) NOT APPLICABLE

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☒ Others (Specify) NON-LEAKING

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify) INSTALLED 3" BALL VALVE

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☒ Others (Specify) NON-LEAKING

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
 Dead floating crabs Withering of vegetation ☒ Others (Specify) NON-LEAKING

iii. Delineation of Impacted area NOT APPLICABLE

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact NOT APPLICABLE

(a) Community (Indicate name)

- i.
 ii.
 iii.
 iv.

(b) Land (Indicate area in m²)

- i.
 ii.
 iii.
 iv.

(c) Creek/Creek lets

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... NOT APPLICABLE

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation..... SPDC SHOULD ENSURE TO REPAIR
THE AFFECTED SECTION OF THE PIPELINE. SPDC SHOULD
INCREASE SURVEILLANCE ALONG THE FACILITY.....

12. Time Investigation ended..... 1552 HRS