

Inc. no. 2023/CA/244



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: KLAC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 21/08/2023 ii. Date first reported: 21/08/2023
iii. Date of first investigation: 21/08/2023
iv. Date of follow-up investigation:
v. Time investigation started: 15:02 hrs
vi. Estimated quantity spilled: 0.6 bbl

4. Site Details

- i. Site/Location: 14" AKI - Ebocha P/K @ Mgbe
ii. Position of Spill/Leak: N 05° 28' 34.4" E 056° 42' 05.4"
iii. Spill area
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid

Attempted re-entry for a repair of cone head was
cut, with and a hacksaw of 140mm was seen

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify) *ref*

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
 Dead floating crabs Withering of vegetation Others (Specify) *ref*

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. *Mgbeke*

ii.

iii.

iv.

(b) Land (Indicate area in m²)

i. *31 m²*

ii.

iii.

iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>
<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>	<i>[Handwritten]</i>

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... *NA*

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation.....

There is need to improve security and surveillance.

12. Time Investigation ended.....

16-10-10