



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: PPMC
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 25/07/2013 ii. Date first reported:.....
 - iii. Date of first investigation: 29/07/2013
 - iv. Date of follow-up investigation:.....
 - v. Time investigation started: 1:05 PM
 - vi. Estimated quantity spilled:.....
4. Site Details
 - i. Site/Location: Km 14 Keke Village, Chikun LGA, Kaduna State
 - ii. Position of Spill/Leak: N 10° 51' 84.0", E 007° 51' 87.8", Z = 622m
 - iii. Spill area
☒ Land ☐ Swamp ☒ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☒ Others (specify) River
 - iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
 - ii. Type of Oil contaminant
☐ Crude Oil ☐ Condensate ☐ Chemicals ☒ Refined Products
☒ Others (specify) AGO
 - iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
 - iv. Cause Of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....
 - v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☒ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify).....

6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☒ Surface water
☐ Venerable Objects ☒ Others (specify) River course

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☒ Withering of vegetation ☐ Others

iii. Delineation of impacted area

- ☐ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m^2)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☐ Mapping

9. Samples taken.... NA

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation... Observe and monitor the washed oil along the river and report to the Agency in their risk base assessment report.

12. Time investigation ended... 1:32 PM

13. Name and Signature of Participants

❖ NOSDRA

1. Mutskow Alexander Danladi 29/7/2013
 2. Uman Aminu Musa 29/07/2013
 3. AUDU MICHAEL IDU 29/07/2013
 4. Sahin Oyiza Mary 29/7/13
 5. Juddum Ali Durrani 29/7/13
 6. ABDULKARIM ABDUL 29/7/13

❖ DPR

1. FEP
 2.
 3.

❖ STATE MINISTRY OF ENVIRONMENT

1. SAMIMOTS KEPA 29/7/13 08030531155
 2. BETTY Nwachukwu FM ENV 29/7/13
 3. 08036826143

❖ LOCAL GOVERNMENT COUNCIL

1.
 2.
 3.

❖ COMPANY

1. OBETA J.C/PPMC 29/7/13
 2.
 3.

❖ COMMUNITY

1.
 2.
 3.