



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This JIV Form is to be completed and signed by all participating parties in the field*

1. Company: PPME ABASI
2. Type of Complaint/Incident:  
☒ Oil Pollution    ☐ Fire/Explosion    ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify).....
3. Incident Details  
i. Date of Incident: 24/07/13    ii. Date first reported: 25/07/13  
iii. Date of first investigation: 13/08/13  
iv. Date of follow-up investigation:.....  
v. Time investigation started: 11:33 am  
vi. Estimated quantity spilled: Unknown
4. Site Details  
i. Site/Location: Km 72.8 ABASI  
ii. Position of Spill/Leak: N 08. 61342°, E 006. 91274°  
iii. Spill area  
☒ Land    ☐ Swamp    ☐ Freshwater    ☐ Mangrove    ☐ Coastline  
☐ Near shore    ☐ Offshore    ☐ Others (specify).....  
iv. Structural Controls in Place  
☐ Boom    ☐ Trenches    ☐ Bund wall    ☐ Sorbents    ☐ Others (specify)..... pegging & clamping
5. Circumstances Around Spill Point  
i. Visual observation of Hole Position  
☒ 12 O' Clock    ☐ 10 O' Clock    ☐ 2 O' Clock    ☐ 3 O' Clock  
☐ 4 O' Clock    ☐ 5 O' Clock    ☐ 6 O' Clock  
ii. Type of Oil contaminant  
☒ Crude Oil    ☐ Condensate    ☐ Chemicals    ☐ Refined Products  
☐ Others (specify) .....
- iii. Facility  
☒ Pipeline    ☐ Flow line    ☐ Wellhead    ☐ Manifold    ☐ Flow Station    ☐ Rig  
☐ Storage Tank    ☐ Compressor Plant    ☐ Others (specify).....
- iv. Cause Of Spill  
☐ Corrosion    ☒ Equipment Failure    ☐ Third Party Interference    ☐ Accident  
☐ Operational Error    ☐ Others (specify).....
- v. Visible Sign of Third Party Interference  
☐ Hacksaw Marks    ☐ Drilled Holes    ☐ Blasting    ☐ Theft    ☐ Acid  
☐ Others (specify).....

## 6. Impact of Incident

### i Properties impacted by the incident

☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water  
☐ Venerable Objects ☐ Others (specify).....

### ii. Nature of impact

☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes  
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

### iii. Delineation of impacted area

☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

## 7. Extent of Impact

### a) Community (indicate name)

i. ....  
 ii. ....  
 iii. ....  
 iv. ....

### b) Land (indicate area in m<sup>2</sup>)

i. ....  
 ii. ....  
 iii. ....  
 iv. ....

### b) Creeks/Creek lets ☐ Tidal ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### c) Swamp ☐ Tidal ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### d) River ☐ Tidal ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### e) Shoreline/water

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken..... None

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation..... Site should be cleaned up, remedied and properly buried ASAP

12. Time investigation ended..... 11:50 am.

13. Name and Signature of Participants

❖ NOSDRA

1. Hiron usman [Signature] 13/08/13  
2. Porro Musu [Signature] 13/08/13  
3. ABDulkadir Abdul [Signature] 13/08/13

❖ DPR

1.  
2.  
3.

❖ STATE MINISTRY OF ENVIRONMENT

1.  
2.  
3.

❖ LOCAL GOVERNMENT COUNCIL

1.  
2.  
3.

❖ COMPANY

1. NMDC/PPMC ABASI PUMP STATION.  
2. Goma M.A. [Signature]  
3.

❖ COMMUNITY

1.  
2.  
3.