

189

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation..... IMPROVE SURVEILLANCE
ON FACILITY

12. Time Investigation ended..... 15:45 PM