

ID: 1724324



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify)

3. Incident Details

- i. Date of Incident: 01/12/2023 ii. Date first reported: 01/12/2023
iii. Date of first investigation: 02/12/2023
iv. Date of follow-up investigation: N/A
v. Time investigation started: 01:15 PM
vi. Estimated quantity spilled: 34 bbls

4. Site Details

- i. Site/Location: 20" KC - Rumedape TL @ Owerreware, Abia/Odua, Rivers State
ii. Position of Spill/Leak: N4.96024985 E 6.58295775
iii. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (Specify)
iv. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☐ Others (Specify) NONE

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☒ 10 O'Clock ☒ 2 O'Clock ☒ 3 O'Clock
☒ 4 O'Clock ☒ 5 O'Clock ☒ 6 O'Clock 9 O'clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (Specify)

iii. Facility

- ☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant
☒ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (Specify) Unknown persons tampered with newly

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid

clamped 20" line @ 9 O'clock.

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken... N/A

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation... Increase in surveillance, Repairs were carried out immediately after Jw. Need for urgent recovery and clean-up

12. Time Investigation ended... 02:52 pm

13. Name and Signature of Participants

❖ NOSDRA

1. IDOKO TIMOTHY CHIDI 2/12/2023 [Signature]

2. /

3. /

❖ NUPRC/NMDPRA

1. /

2. /

3. /

❖ STATE MINISTRY OF ENVIRONMENT

1. DR. TOMBARI BODO [Signature] 02-12-23

2. /

3. /

❖ LOCAL GOVERNMENT COUNCIL

1. /

2. /

3. /

❖ COMPANY

1. CHUKA MANUELLIM [Signature] 02/12/2023

2. OKOYE ELIZABETH [Signature] 02/12/2023

3. /

❖ COMMUNITY

1. OYE HOLAY 02-12-23 [Signature]

2. /

3. /

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken... *N/A*

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation... *Increase in Surveillance, Repairs were*

carried out immediately after JN.

Need for urgent recovery and clean-up

12. Time Investigation ended... *02:52 pm*