

2023-1738393



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident:

- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify) NON-LEAK

3. Incident Details

- i. Date of Incident: 04-12-23 ii. Date first reported: 04-12-2023
 iii. Date of first investigation: 30-12-2023
 iv. Date of follow-up investigation:
 v. Time investigation started: 12:35 PM
 vi. Estimated quantity spilled: NON-LEAK

4. Site Details

- i. Site/Location: OLD 20" KOLOCREEK - RUMURE P/LINE AT OUPOR
NO COMMUNITY, APPROX EAST KSA
 ii. Position of Spill/Leak: N 4° 58' 13.432" E 6° 38' 10.763"

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) N/A

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify) NON-LEAKS

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify) SABOTAGE

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid

3" BALL VALVE AT 12 O' CLOCK POSITION ON
Pipeline BT HILKOWA (P/S 246)

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify) N/A

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) N/A

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m²)

- i. [Handwritten Signature] i. [Handwritten Signature]
 ii. [Handwritten Signature] ii. [Handwritten Signature]
 iii. [Handwritten Signature] iii. [Handwritten Signature]
 iv. [Handwritten Signature] iv. [Handwritten Signature]

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... *N/A*

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation. *Repair should commence immediately. Surveillance to be intensive on the pipeline Right of way (ROW).*

12. Time Investigation ended. *1:45pm*