

INCIDENT NO 2023/LAR/329



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NIGERIA AGRI OIL COMPANY

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 29/12/2023 ii. Date first reported: 29/12/2023
iii. Date of first investigation: 29/12/2023
iv. Date of follow-up investigation: 21/01/2024
v. Time investigation started: 13:41RS
vi. Estimated quantity spilled: 8.32 BARRELS

4. Site Details

- i. Site/Location: 24th OCEAN - BRAS PL AT OYI GBA, AWEKA R/S
ii. Position of Spill/Leak:
iii. Spill area
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)
iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O'Clock ☒ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock 9-11 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☒ Others (Specify) 190MM HACKSAW CUT

6. Impact of Incident

i. Properties Impacted by the Incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify)

ii. Nature of Impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
 Dead floating crabs Withering of vegetation ☒ Others (Specify) *Dead vegetation*

iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. *OYIGBA Community*

(b) Land (Indicate area in m²)

i. *341.83 m²*

- ii.
 iii.
 iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten arrow pointing up-right]</i>	<i>[Handwritten arrow pointing up-right]</i>	<i>[Handwritten arrow pointing up-right]</i>	<i>[Handwritten arrow pointing up-right]</i>

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten arrow pointing up-right]</i>	<i>[Handwritten arrow pointing up-right]</i>	<i>[Handwritten arrow pointing up-right]</i>	<i>[Handwritten arrow pointing up-right]</i>

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten arrow pointing up-right]</i>	<i>[Handwritten arrow pointing up-right]</i>	<i>[Handwritten arrow pointing up-right]</i>	<i>[Handwritten arrow pointing up-right]</i>

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten arrow pointing up-right]</i>	<i>[Handwritten arrow pointing up-right]</i>	<i>[Handwritten arrow pointing up-right]</i>	<i>[Handwritten arrow pointing up-right]</i>

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☒ Mapping

9. Samples taken.....

10. Investigation carried out by

☐ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation.

NAOC SHOULD MAKE PLAN TO
REMEDIATE / CLEAN UP THE AREA, TO STOP
THE IMPACT FROM REACHING GROUND-WATER
IF BOTH ARE