

2024-1940224

**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident:

- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify) NON-LEAK

3. Incident Details

- i. Date of Incident: 01:02:24 ii. Date first reported: 02:02:24  
iii. Date of first investigation: 05:02:24  
iv. Date of follow-up investigation: \_\_\_\_\_  
v. Time investigation started: \_\_\_\_\_  
vi. Estimated quantity spilled: NON-LEAK (NIL)

4. Site Details

- i. Site/Location: 20" RHITHALPE - NIPOKA P/LINE AT IBAA  
COMMUNITY, ENCHWA FTA, 12/5  
ii. Position of Spill/Leak: NA-953151 E-6.850139

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline  
☐ Near shore ☐ Offshore ☐ Others (Specify) NON-LEAK

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) NON-LEAK

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock  
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products  
☐ Others (Specify) NON-LEAK

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig  
☐ Storage Tank ☐ Compressor Plant  
☐ Others (Specify) \_\_\_\_\_

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☐ Third Party Interference ☐ Accident  
☐ Operational Error ☐ Others (Specify) SABOTAGE

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid

3" BALL VALVE INCISED ON THE PIPELINE  
AT 12 O'CLOCK POSITION BY UNKNOWN  
PERSON(S)

## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☐ Farmland   ☐ Fish Pond   ☐ Vegetation   ☐ Fishing Net   ☐ Surface water  
☐ Venerable Objects   ☐ Others (Specify) ... NOY - LEAK ...

### ii. Nature of impact

- ☐ Oil stained vegetation   ☐ Oil stained fishing nets   ☐ Dead floating fishes  
 Dead floating crabs   Withering of vegetation   Others (Specify) NOY - LEAK

### iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW   ☐ Outside Company's facility/ROW

## 7. Extent of Impact

### (a) Community (Indicate name)

- i. ....  
 ii. ....  
 iii. ....  
 iv. ....

### (b) Land (Indicate area in m<sup>2</sup>)

- i. ....  
 ii. ....  
 iii. ....  
 iv. ....

### (c) Creek/Creek lets

- ☐ Tidal   ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (d) Swamp

- ☐ Tidal   ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (e) River

- ☐ Tidal   ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (f) Shoreline/water

- ☐ Tidal   ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs    ☐ Video coverage    ☐ Mapping

9. Samples taken..... N/A .....

10. Investigation carried out by

☒ Foot    ☐ Boat    ☐ Aircraft

11. Remarks/Recommendation ~~SEE~~ SPOC SHOULD START REPAIRS  
OF INCIDENT. POINT IMMEDIATELY. SECONDLY, TO  
INCREASE SECURITY ON THEIR PIPELINE RIGHT OF  
WAY.

12. Time Investigation ended..... 2:18 PM .....