

INCIDENT NUMBER: 2024/NL/LAR/015



## NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

### JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NATIONAL AGIP OIL COMPANY (NAPCO)

#### 2. Type of Complaint/Incident:

- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution  
☒ Others (Specify) NON LEAK

#### 3. Incident Details

- i. Date of Incident: 18<sup>TH</sup> FEB, 2024 ii. Date first reported: 18<sup>TH</sup> FEB, 2024  
iii. Date of first investigation: 19<sup>TH</sup> FEBRUARY, 2024  
iv. Date of follow-up investigation: NIL  
v. Time investigation started: 16:35 HRS  
vi. Estimated quantity spilled: NIL

#### 4. Site Details

- i. Site/Location: 8" OBIATU 4344 FLOWLINE @ OBRKOM  
ii. Position of Spill/Leak: N 05 23' 38.9" E 006' 38' 23.3" (2' clock)  
iii. Spill area  
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline  
☐ Near shore ☐ Offshore ☐ Others (Specify).....  
iv. Structural Controls in Place  
☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☒ Others (Specify) NIL

#### 5. Circumstances Around Spill Point

##### i. Visual observation of Hole Position

- ☐ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock  
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

##### ii. Type of Oil Contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products  
☒ Others (Specify) NON LEAK

##### iii. Facility

- ☐ Pipeline ☒ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig  
☐ Storage Tank ☐ Compressor Plant  
☐ Others (Specify) .....

##### iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☐ Third Party Interference ☐ Accident  
☐ Operational Error ☒ Others (Specify) NON LEAK

##### v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid

## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☐ Farmland   ☐ Fish Pond   ☐ Vegetation   ☐ Fishing Net   ☐ Surface water  
☐ Venerable Objects   ☒ Others (Specify) ... NO OIL LEAK .....

### ii. Nature of impact

- ☐ Oil stained vegetation   ☐ Oil stained fishing nets   ☐ Dead floating fishes  
 Dead floating crabs   Withering of vegetation   Others (Specify) ... NO OIL LEAK ...

### iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW   ☒ Outside Company's facility/ROW

## 7. Extent of Impact

### (a) Community (Indicate name)

i. 8" OBIATU

ii. /

iii. /

iv. /

### (b) Land (Indicate area in m<sup>2</sup>)

i. NIL

ii. /

iii. /

iv. /

### (c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
| /    | /                  | /               | /              |
| /    | /                  | /               | /              |
| /    | /                  | /               | /              |
| /    | /                  | /               | /              |

### (d) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
| /    | /                  | /               | /              |
| /    | /                  | /               | /              |
| /    | /                  | /               | /              |
| /    | /                  | /               | /              |

### (e) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
| /    | /                  | /               | /              |
| /    | /                  | /               | /              |
| /    | /                  | /               | /              |
| /    | /                  | /               | /              |

### (f) Shoreline/water

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
| /    | /                  | /               | /              |
| /    | /                  | /               | /              |
| /    | /                  | /               | /              |
| /    | /                  | /               | /              |

8. Photograph/Map/Chart Ref.

☒ Still photographs    ☐ Video coverage    ☐ Mapping

9. Samples taken.....NIL.....

10. Investigation carried out by

☒ Foot    ☐ Boat    ☐ Aircraft

11. Remarks/Recommendation.....INCREASE SURVEILLANCE  
ON THE FLOW LINES AND SUSTAINED  
PROMPT RESPONSE TO OIL SPILL INCIDENTS.....

12. Time Investigation ended.....18:00 HRS.....