



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIA AGIP OIL COMPANY (NAOC) LIMITED
2. Type of Complaint/Incident:
☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify).....
3. Incident Details
i. Date of Incident: 17/03/2024 ii. Date first reported: 17/03/2024
iii. Date of first investigation: 17/03/2024 iv. Spill Incident No.: 2024/SAR/057
v. Date of follow-up investigation: vi. Time investigation started: 14:37 HRS
vii. Estimated quantity spilled(bbls): 0.15 BBL viii. Quantity Recovered: MOPPED UP
4. Site Details
i. Site/Location: 6" OGBOINBIRI/TEBIDABA P/L AT KROKROSEI
ii. State: BAYELSA iii. L.G.A.: SOUTHERN IJAW
iv. Spill Co-Ordinates: N(m) 04° 44' 29.4"
E(m) 005° 58' 32.6"
v. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☐ Others (specify) SEASONAL SWAMP
iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify).....
iii. Facility
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☐ Others (specify).....
iv. Cause of Spill
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify).....
v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify) VANDALS INSTALLED 2" NIPPLE ON THE FACILITY AT 12 O'CLOCK POSITION FOR CRUDE OIL THEFT ACTIVITIES.

6. Impact of Incident

i Properties impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
 ☒ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
 ☒ Withering of vegetation
 ☒ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops
 ☒ Fish Farm/ Pond
 ☒ Fishing Net
 ☒ Makeshift
☒ Permanent
 ☒ Others VEGETATION

8. Extent of Impact

a) Community (indicate name)

- i. KROKROSEI
 ii. _____
 iii. _____
 iv. _____

b) Land (indicate area in m²)

- i. 237.282 M²
 ii. _____
 iii. _____
 iv. _____

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. ~~Photograph~~/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken.....

N/A

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation.....

ENHANCED SURVEILLANCE
AND SECURITY REQUIRED BOTH WITHIN AND
OUTSIDE THE COMPANY'S ROW