



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIA AGIP OIL COMPANY (NAOC) LIMITED

2. Type of Complaint/Incident:

☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution

☒ Others (Specify).....

3. Incident Details

i. Date of Incident: 22/03/2024 ii. Date first reported: 22/03/2024

iii. Date of first investigation: 22/03/2024 iv. Spill Incident No: 2024/SAR/063

v. Date of follow-up investigation: / /

vi. Time investigation started: 18:08 HRS

vii. Estimated quantity spilled(bbls): 0.14 BBL viii. Quantity Recovered: MOPPED UP

4. Site Details

i. Site/Location: 6" OGBOINBIRITE BIDABA P/L AT OKOTUMARI

ii. State: BAYELSA iii. L.G.A: SOUTHERN IJAW

iv. Spill Co-Ordinates: N(m) 04° 45' 38.9"
E(m) 005° 58' 40.0"

v. Spill area

☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline

☒ Near shore ☒ Offshore ☒ Others (specify) SEASONAL SWAMP

iv. Structural Controls in Place

☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify) NIL

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock

☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock

ii. Type of Oil contaminant

☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products

☒ Others (specify)

iii. Facility

☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig

☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....

iv. Cause of Spill

☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident

☒ Operational Error ☒ Others (specify).....

v. Visible Sign of Third Party Interference

☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid

☒ Others (specify) 2" VALVE WAS INSTALLED ON THE FACILITY AT 12 O'CLOCK POSITION BY THIRD PARTY FOR CRUDE OIL THEFT ACTIVITIES.

6. Impact of Incident

i. Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops ☒ Fish Farm/ Pond ☒ Fishing Net ☒ Makeshift
☒ Permanent ☒ Others **VEGETATION**

8. Extent of Impact

a) Community (indicate name)

- i. **Okputuwar**
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i. **215-116 M²**
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs

☒ Video coverage

☒ Mapping

10. Samples taken..... NIL

11. Investigation carried out by

☒ Foot

☒ Boat

☒ Aircraft

12. Remarks/Recommendation..... IMPROVED SURVEILLANCE AND SECURITY
BOTH WITHIN & OUTSIDE THE COMPANY'S ROW
REQUIRED