



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY LIMITED (NAOC)

2. Type of Complaint/Incident:

☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution

☒ Others (Specify).....

3. Incident Details

i. Date of Incident: 09/03/2024 ii. Date first reported: 09/03/2024

iii. Date of first investigation: 09/03/2024 iv. Spill Incident No.: 2024/SAR/051

v. Date of follow-up investigation: —/—/—

vi. Time investigation started: 12:34 HRS

vii. Estimated quantity spilled(bbls): 0.07184 viii. Quantity Recovered:.....

4. Site Details

i. Site/Location: 18" TERIBABA/BRASS PIPELINE AT LAGOSGBENE

ii. State: BAYELSA iii. L.G.A: SOUTHERN ITAW

iv. Spill Co-Ordinates: N(m) 04° 27' 53.4"
E(m) 006° 09' 42.0"

v. Spill area

☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline

☒ Near shore ☒ Offshore ☒ Others (specify).....

iv. Structural Controls in Place

☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify) NONE

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock

☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock

ii. Type of Oil contaminant

☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products

☒ Others (specify).....

iii. Facility

☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig

☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....

iv. Cause of Spill

☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident

☒ Operational Error ☒ Others (specify).....

v. Visible Sign of Third Party Interference

☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid

☒ Others (specify).....

6. Impact of Incident

i Properties impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
☒ Others (specify) ... NONE

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
☒ Withering of vegetation
☒ Others... NONE

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW
☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops
☒ Fish Farm/ Pond
☒ Fishing Net
☒ Makeshift
☒ Permanent
☒ Others ... NONE

8. Extent of Impact

a) Community (indicate name)

- i. LAGOS GREENE
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i. 7.15 M²
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken..... N/A

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation NAOC SHOULD INTENSIFY SECURITY
ON HER FACILITIES.

13. Time investigation ended... 14:42 HRS

14. Name and Signature of Participants