

2024-2212172



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPOC

2. Type of Complaint/Incident:

- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify) NON-LEAKING

3. Incident Details

- i. Date of Incident: 11-04-2024 ii. Date first reported: 12-04-2024
iii. Date of first investigation: 13-04-2024
iv. Date of follow-up investigation: _____
v. Time investigation started: 15:55 Hrs
vi. Estimated quantity spilled: WATER LEAK

4. Site Details

- i. Site/Location: 14" OKORDIA - RUMUWASE P/LINE AT OSHI
COMM UNIT, ANKARA INLET LGA, NIS
ii. Position of Spill/Leak: N5.10226 E6.51347
iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify) _____

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) WATER LEAK

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock ☒ 10-12 O'Clock
Position

ii. Type of Oil Contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify) WATER LEAK

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify) _____

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify) SABOTAGE

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid

OBSERVED ABOUT 170MM HACKSAW CUT (WATER LEAK)
IN THE PIPELINE AT 10-12 O'Clock Position

6. Impact of Incident

i. Properties Impacted by the incident

☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water

☐ Venerable Objects

☐ Others (Specify) WATER LEAK

ii. Nature of impact

☐ Oil stained vegetation

☐ Oil stained fishing nets

☐ Dead floating fishes

Dead floating crabs

Withering of vegetation

Others (Specify) WATER LEAK

iii. Delineation of Impacted area

☒ Within Company's facility/ROW

☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m²)

i. [Handwritten Signature]

i. [Handwritten Signature]

ii. [Handwritten Signature]

ii. [Handwritten Signature]

iii. [Handwritten Signature]

iii. [Handwritten Signature]

iv. [Handwritten Signature]

iv. [Handwritten Signature]

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>
<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>	<u>[Handwritten Signature]</u>

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken. NO SAMPLES COLLECTED AT THE TIME OF

JIN
10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation. SPDC INNS Mandated to carry out
repairs on the pipeline as soon as possible.
Surveillance should be intensified on the pipeline
right of way (ROW). 15:49 hrs

12. Time Investigation ended

