



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NAOC

INCIDENT NO: 2015/SAR/126/176

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify) GAS & CONDENSATE

3. Incident Details

i. Date of Incident: 08-05-2015 ii. Date first reported: 08-05-2015

iii. Date of first investigation: 09-05-2015

iv. Date of follow-up investigation:

v. Time investigation started: 15.30 HOURS

vi. Estimated quantity spilled: N/A (GAS) 0.006 BBL CONDENSATE

4. Site Details

OGBOINBIRI 9SS FLOW LINE OGBOINBIRI
SATELLITE MANIFOLD @ OGBOINBIRI

i. Site/Location:

ii. Position of Spill/Leak: 6 O'CLOCK

N 04° 49' 31.5"
E 005° 58' 19.2"

iii. Spill area

- ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (Specify)

iv. Structural Controls in Place

- ☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☒ 10 O'Clock ☒ 2 O'Clock ☒ 3 O'Clock
☒ 4 O'Clock ☒ 5 O'Clock ☒ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (Specify) GAS

iii. Facility

- ☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant
☒ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (Specify) RUPTURED PIPE (PIN HOLE)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☐ Acid
☒ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the Incident

☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water

☒ Venerable Objects ☒ Others (Specify)

ii. Nature of impact

☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes

☒ Dead floating crabs ☒ Withering of vegetation ☒ Others (Specify)

iii. Delineation of Impacted area

☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i.

ii.

iii.

iv.

(b) Land (Indicate area in m²)

i.

ii.

iii.

iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken..... **NO**

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation. **① REPAIR OF MANIFOLD**

12. Time Investigation ended.....