



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This JIV form is to be completed and signed by all participating parties in the field*

1. Company: NAOC

2. Type of Complaint/Incident:

- ☐ Oil Pollution    ☐ Fire/Explosion    ☐ Drilling Mud/Chemical Pollution  
☒ Others (Specify) GASEOUS EMISSION

3. Incident Details

- i. Date of Incident: 09/02/2015    ii. Date first reported: 09/02/2015  
iii. Date of first investigation: 10/02/2015  
iv. Date of follow-up investigation: 10/02/2015  
v. Time investigation started: 11:40 HRS  
vi. Estimated quantity spilled: .....

4. Site Details

- i. Site/Location: 2015/LAR/016 1049  
EBOCHA GL WELL HEAD, WELLHEAD LOCATION, OBRIKOM ONE LGA, R/S  
ii. Position of Spill/Leak: N 05° 29' 30.0", E 006° 39' 15.4"

iii. Spill area

- ☒ Land    ☐ Swamp    ☐ Freshwater    ☐ Mangrove    ☐ Coastline  
☐ Near shore    ☐ Offshore    ☐ Others (Specify) .....

iv. Structural Controls in Place

- ☐ Boom    ☐ Trenches    ☐ Bund Wall    ☐ Sorbents    ☐ Others (Specify) .....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 0'Clock    ☐ 10 0'Clock    ☐ 2 0'Clock    ☐ 3 0'Clock  
☐ 4 0'Clock    ☐ 5 0'Clock    ☐ 6 0'Clock    11 0'clock

ii. Type of Oil Contaminant

- ☐ Crude Oil    ☐ Condensate    ☐ Chemicals    ☐ Refined Products  
☐ Others (Specify) PRODUCTION SPOOL

iii. Facility

- ☐ Pipeline    ☐ Flow Line    ☐ Wellhead    ☐ Manifold    ☐ Flow Station    ☐ Rig  
☐ Storage Tank    ☐ Compressor Plant  
☐ Others (Specify) PRODUCTION SPOOL

iv. Cause of Spill

- ☐ Corrosion    ☒ Equipment Failure    ☐ Third Party Interference    ☐ Accident  
☐ Operational Error    ☐ Others (Specify) .....

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks    ☐ Drilled Holes    ☐ Blasting    ☐ Theft    ☐ Acid  
☐ Others (Specify) .....