

73

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: P.P.M.C

2. Type of Complaint/Incident:

☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution

☐ Others (Specify)

3. Incident Details

i. Date of Incident: 13-04-2015 ii. Date first reported: 13-04-2015

iii. Date of first investigation: 12-05-2015

iv. Date of follow-up investigation:

v. Time investigation started: 14:30 - 14:50 Hrs

vi. Estimated quantity spilled:

4. Site Details

i. Site/Location: Km 42.5 KANGIMI KAD-ZARIA AXIS

ii. Position of Spill/Leak: N 10.77045 E 007.58761 619.7m

iii. Spill area

☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline

☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) WELDER

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☐ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☒ 3 O'Clock

☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

☐ Crude Oil ☐ Condensate ☐ Chemicals ☒ Refined Products

☐ Others (Specify)

iii. Facility

☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig

☐ Storage Tank ☐ Compressor Plant

☐ Others (Specify)

iv. Cause of Spill

☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident

☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid

☐ Others (Specify)

6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☒ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m^2)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☐ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☐ Foot ☐ Boat ☐ Aircraft



11. Remarks/Recommendation. Affected land and water
should be properly cleaned up.

Security surveillance along the pipeline should be improved

12. Time investigation ended..... 14:50pm

13. Name and Signature of Participants

❖ NOSDRA

1. GUYIT ABEL DELLONG ESI 
2. NURA MOHD. ADAM ESI 
3.

❖ DPR

1.
2.
3.


❖ STATE MINISTRY OF ENVIRONMENT

1.
2.
3.



❖ LOCAL GOVERNMENT COUNCIL

1.
2.
3.

❖ COMPANY PPmc

1. JAJA A-N  13/5/18
2.
3.

❖ COMMUNITY

1. MUKTAR ILYASU 
2. Adamu YAU 
3.